

ENVIRONMENTAL INSPECTION REPORT

Permittee: (complete name and address) Burnstone Ventures Inc. Attn: Eugene Beukman

Suite 800-1199 West Hastings St, Vancouver, BC, V6E-3T5

		Permit Expiry Date	Last Previous Inspection
Land Use Permit No.	N2007C0014	June 19/13	by RMO: July 14/09
Quarrying Permit No.	n/a		
Water Licence	2BE-BAF1116		
Contractor:	Apex Geosciences (to be confirmed)	Subcontractor:	

Location(s) Inspected: Ericksen Lake Project → Main Camp + Airstrip

at N 70° 56' 05" , W 80° 11' 00" (NAD 83)

Current Stage of Operation: No activity; No cleanup has occurred and camp has not been monitored

in some time (ie signs of human presence / ^{possible} vandalism). Site is a huge mess.

Program Modifications Approved: Extension to LUP granted Apr 19/12 to allow additional time for

site restoration + cleanup.

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable

	Operating Condition	Aspect Inspected			
A	Location as Permitted	A	As permitted in original application		
B	Timing as Permitted	U	Cleanup has not yet occurred; Inspector has not received		
	Equipment as Approved	MB N/I	(as permitted in) MO notification prior to commencement		
D	Methods & Techniques	—	Unknown		
E	Facilities	U	All but 2 weather havers have been stripped / Debris everywhere		
F	Erosion	—	Natural erosion occurring at airstrip and path from airstrip to camp		
G	Chemicals, Waste	U			
H	Wildlife & Fisheries Habitat	U	Waste + chemicals are accessible to wildlife		
I	Ecological Resource	—	Unknown		
K	Fuel Storage	U	No secondary containment, no monitoring → see ^{other} comments (pg 2)		
L	Brush Disposal	n/a			
M	Matters Not Inconsistent	n/a			
N	Water Engineering	n/a			
O	Water Supply	U	No water being withdrawn → garbage / debris blowing into lake		
P	Restoration	U	Cleanup has not yet occurred		
Q	Quarrying Methods	n/a			
R	Sections 12 to 19 T.L.U.R.	—	Unknown		
S					
T	*Contaminated soil left in drums at airstrip → left exposed to the elements.				

Surveillance Network Program

Explanatory Remarks (attach page 2, if required) Airstrip is in bad shape → approx. 60 full drums of fuel

at airstrip alone; more at main camp (plus 20-30 empties)

• Salt contamination where CaCl₂ (Calcium Chloride) bags have been left

exposed to weather

Page 2 attached ☒ Yes ☐ No

Representative's Signature

Inspector's Signature

RMO Initials

District Mgr. Initials

Representative's Title