



Field Operations  
Nunavut Regional Office  
PO Box 100  
Iqaluit, NU X0A 0H0

August 20, 2012

Eugene Beukman, VP Administration  
Burnstone Ventures Inc.  
800-1199 West Hastings St.  
Vancouver, British Columbia V6E 3T5  
Email: [ebeukman@pendergroup.ca](mailto:ebeukman@pendergroup.ca)

RE: NWB Licence No. 2BE-CYG0406

Dear Mr. Beukman,

I was present at your Cygnet Lake site on July 15, 2012. Please find attached the report of my inspection. Some wooden debris and empty barrels were found on-site and will need to be removed. Please contact me to discuss a timeline for completion.

A hard copy of this report will follow in the mail.

Thank you,

Eva Paul  
Water Resources Officer

Phone: 867-975-4548  
Fax: 867-979-6445  
Mobile: 867-222-6490  
E-mail: [Eva.Paul@aadnc-aadnc.gc.ca](mailto:Eva.Paul@aadnc-aadnc.gc.ca)

Cc: Andrew Keim, A/Manager, Field Operations, Nunavut Regional Office  
Phyllis Beaulieu, Manager of Licensing, Nunavut Water Board



## WATER USE INSPECTION FORM

Date: July 15 2012	Licensee Rep. (Name/Title): N/A
Licensee: Burnstone Ventures	Licence No.: 2BE-CYG0406

### WATER SUPPLY

Source(s): NA	Quantity used: n/a
Owner:/Operator: Licencee	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NA	Storage Structure: NA	Treatment Systems: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

**Comments:** No evidence of a camp at this site. A few core boxes are all that are present.

### WASTE DISPOSAL

**Sewage:** Sewage Treatment System (Prim./Sec/Ter.): N/A

Natural Water Body: -	Continuous Discharge (land or water): -	
Seasonal Discharge: -	Wetlands Treatment: -	Trench: -

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: NA
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NA	A&R Plan: NA
Discharge: NA	Effluent Discharge Rate: NA	

**Comments:** N/A

### Solid Waste:

**Owner/Operator:**

Landfill: NA	Burn & Landfill: NA	Other: Backhaul
--------------	---------------------	-----------------

**Comments:**

Some wooden debris present at camp location: N67 36 36.0 W110 45 05.0

8 old drums, empty, at the location marked in the file as the fuel cache for this project:

N67 39 42.9 W110 50 20.2

### FUEL STORAGE:

**Waste Oil Storage:**

None

**Owner/Operator:** Licensee

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: U	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

**Comments:**

### Non-Compliance of Act or Licence:

Barrels should have been backhauled at the conclusion of the project.

### Action Required:

- Licencee is to contact the inspector (undersigned) by September 7, 2012 to discuss a date when the debris and barrels will be removed.

Eva Paul

Inspector's Name

Inspector's Signature





**Figure 1. Wooden debris found at N67 36 36.0 W110 45 05.0**



**Figure 2. Barrels seen at N67 39 42.9 W110 50 20.2. Two other barrels present, along the shore.**