



Field Operations  
Nunavut Regional Office  
PO Box 100  
Iqaluit, NU X0A 0H0

August 20, 2012

Eugene Beukman, VP Administration  
Burnstone Ventures Inc.  
800-1199 West Hastings St.  
Vancouver, British Columbia V6E 3T5  
Email: [ebeukman@pendergroup.ca](mailto:ebeukman@pendergroup.ca)

RE: NWB Licence No. 2BE-CYG0406

Dear Mr. Beukman,

I was present at your Cygnet Lake site on July 15, 2012. Please find attached the report of my inspection. Some wooden debris and empty barrels were found on-site and will need to be removed. Please contact me to discuss a timeline for completion.

A hard copy of this report will follow in the mail.

Thank you,

Eva Paul  
Water Resources Officer

Phone: 867-975-4548  
Fax: 867-979-6445  
Mobile: 867-222-6490  
E-mail: [Eva.Paul@aadnc-aadnc.gc.ca](mailto:Eva.Paul@aadnc-aadnc.gc.ca)

Cc: Andrew Keim, A/Manager, Field Operations, Nunavut Regional Office  
Phyllis Beaulieu, Manager of Licensing, Nunavut Water Board



## WATER USE INSPECTION FORM

|                              |                                 |
|------------------------------|---------------------------------|
| Date: July 15 2012           | Licensee Rep. (Name/Title): N/A |
| Licensee: Burnstone Ventures | Licence No.: 2BE-CYG0406        |

### WATER SUPPLY

|                           |                    |
|---------------------------|--------------------|
| Source(s): NA             | Quantity used: n/a |
| Owner:/Operator: Licencee |                    |

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

|                       |                       |                       |                      |
|-----------------------|-----------------------|-----------------------|----------------------|
| Intake Facilities: NA | Storage Structure: NA | Treatment Systems: NA | Chemical Storage: NA |
| Flow Meas. Device: NA | Conveyance Lines: NA  | Pumping Stations: NA  | Screen : NA          |

**Comments:** No evidence of a camp at this site. A few core boxes are all that are present.

### WASTE DISPOSAL

**Sewage:** Sewage Treatment System (Prim./Sec/Ter.): N/A

|                       |                                         |           |
|-----------------------|-----------------------------------------|-----------|
| Natural Water Body: - | Continuous Discharge (land or water): - |           |
| Seasonal Discharge: - | Wetlands Treatment: -                   | Trench: - |

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

|                            |                             |              |
|----------------------------|-----------------------------|--------------|
| Discharge Quality: NA      | Decant Structure: NA        | Erosion: NA  |
| Discharge Meas. Device: NA | Dyke Inspection: NA         | Seepages: NA |
| Dams, Dykes: NA            | Freeboard: NA               | Spills: NA   |
| Construction: NA           | O&M Plan: NA                | A&R Plan: NA |
| Discharge: NA              | Effluent Discharge Rate: NA |              |

**Comments:** N/A

### Solid Waste:

**Owner/Operator:**

|              |                     |                 |
|--------------|---------------------|-----------------|
| Landfill: NA | Burn & Landfill: NA | Other: Backhaul |
|--------------|---------------------|-----------------|

**Comments:**

Some wooden debris present at camp location: N67 36 36.0 W110 45 05.0  
8 old drums, empty, at the location marked in the file as the fuel cache for this project:  
N67 39 42.9 W110 50 20.2

### FUEL STORAGE:

**Waste Oil Storage:** None **Owner/Operator:** Licensee

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

|                        |                                    |                       |
|------------------------|------------------------------------|-----------------------|
| Berms & Liners: U      | Water within Berms: NA             | Evidence of Leaks: NA |
| Drainage Pipes: NA     | Pump Station & Catchments Berm: NA |                       |
| Pipeline Condition: NA | Condition of Tanks: NA             |                       |

**Comments:**

### Non-Compliance of Act or Licence:

Barrels should have been backhauled at the conclusion of the project.

### Action Required:

- Licencee is to contact the inspector (undersigned) by September 7, 2012 to discuss a date when the debris and barrels will be removed.

Eva Paul

Inspector's Name

Inspector's Signature



**Figure 1. Wooden debris found at N67 36 36.0 W110 45 05.0**



**Figure 2. Barrels seen at N67 39 42.9 W110 50 20.2. Two other barrels present, along the shore.**