



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee		Licensee Representative	
Adamera Minerals Corp.		Zoe Pratt- Offsite Representative	
Licence No. / Expiry		Representative's Title	
2BE-DUB0812		GIS Technician	
Land / Other Authorizations		Land / Other Authorizations	
		N2008C0030	
		Inspector	
		WRO C. Wilson	
Activities Inspected			
<input type="checkbox"/> Camp	<input checked="" type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other: Water Discharge		<input checked="" type="checkbox"/> Reclamation
			<input type="checkbox"/> Fuel Storage
			<input checked="" type="checkbox"/> Other:

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected			
Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	--		Water Manag. Structures	--		Storage	--	
Flow Measure. Device	--		Culverts / Bridges	--		Spills	--	
Source:	--		Drainage	--		Spill Plan	--	
Water Allotment:	--		Erosion / Sediment	--				
Water Used:	--		Mitigation Measures	--		Administrative		
			Reclamation Activities	U	2	Records	--	
			Materials Storage	--		Reports	U	
Waste Disposal			Signage	--		Plans	U	3
Waste Water	--					Notifications	--	
Solid Waste	--		Monitoring			Other		
Hazardous Waste	--		Sample Collection / Analysis	--				
*The number in the comments field will correspond with specific comments provided below.								
Samples taken by Inspector:			Location(s):					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No								

SECTION 1	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
<p>1. An inspection was conducted on Adamera Minerals Corp.'s (formally Uranium North Resources Ltd.) South Baker Project/ Dubawnt Lake Project on July 22nd, 2014. A final inspection was requested by the permittee under Land Use Permit N2008C0030 (see Appendix 1) which is associated with this water licence undertaking.</p> <p>2. Two drill sites located at N62° 25' 24.1" W101° 23' 39.9" and N62° 32' 23.2" W100° 44' 32.7" were inspected. Though the drill sites were found to be remediated to the satisfaction of the inspector, additional waste and debris was noted (see attached pictures).</p> <p>3. The proponent will clarify its responsibilities to the outpost camp located N62° 44' 50.5" W101° 20' 55.5" on the southern end of Dubawnt Lake. As per the Abandonment and Reclamation Plan (A and R Plan) submitted in 2008, this camp was rented from the Tukto Lodge Ltd. formerly Dubawnt Camps Ltd. The A and R Plan also indicated "All buildings and structures will be dismantled and removed. Wooden structures will be burned and ashes sifted to retrieve non-burnable items which will be removed from site."</p>			
SECTION 2	<input type="checkbox"/> Comments (s. 1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input checked="" type="checkbox"/> Action Required (s. __)
<p>As per PART I item 11 -The Licensee shall remove from the site, all infrastructure and site materials, including all fuel caches, drums, barrels, buildings and contents, docks, water pumps and lines, material and equipment prior to the expiry of this Licence.</p> <p>The Proponent will contact the Inspector by March 20<sup>th</sup>, 2015 to discuss the final reclamation activities and inspection for 2015.</p>			
Licensee or Representative		Inspector's Name	
		WRO Wilson	
Signature		Signature	
Date		Date	
		February 24,2015	

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---





PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
July 22nd, 2014	2BE-DUB0812	Sony DSC-HX50V Cyber shot	WRO Wilson

Locations name:	Lat/Long (DD.MM.SS.SS, NAD83)
PHOTO 1	N62° 25' 34.83", W 101° 21' 30.91"



Description:
Wood and wind blown debris

Locations name:	Lat/Long (DD.MM.SS.SS, NAD83)
PHOTO 2	N62° 32' 30.796", W 100° 44' 44.249"



Description:
Drum





Locations name:		Lat/Long (DD.MM.SS.SS, NAD83)
PHOTO 3		N62 32 27.8, W100 44 39.44
		
<b>Description:</b> Hoses used for drilling		
Locations name:		Lat/Long (DD.MM.SS.SS, NAD83)
PHOTO 4		N62 32 30.9, W100 44 44.297
		
<b>Description:</b> Timbers		