



Water Resources Division
Nunavut Regional Office
Iqaluit, NU X0A 0H0

CIDMS#: 340470

July 8, 2009

Richard Dwyer
License Administrator
P.O. Box 119
Gjoa Haven, NU, X0A 1J0

Re: 2BE-DUB0812 – Annual Report, 2008 – Uranium North Resources Corp. – South Baker/Dubawnt Property

Please be advised that Indian and Northern Affairs Canada (INAC) has completed a review of 2BE-DUB0812 Type “B” Water License 2008 Annual Report for South Baker/Dubawnt Property. The NWB circulated the Report for information purposes only, on April 17, 2009. All associated documents related to this license posted on the NWB ftp site under 2BE-DUB were included in my review (see attached Technical Review Memo).

Should you have any questions or comments, please do not hesitate to contact me at (867) 975-4738 or by email at Andrea.Cull@inac.gc.ca.

Yours truly,

Original Signed By

Andrea Cull
Water Management Specialist

Cc: Kevin Buck – Water Resources Manager, INAC



Technical Review Memorandum

To: Richard Dwyer – License Administrator, NWB
Peter Kusugak – Field Operations Manager, INAC
Allan Armitage, V.P., Exploration, Uranium North Resources Corp.

From: Andrea Cull – Water Management Specialist, INAC

Re: 2BE-DUB0812 – Annual Report, 2008 – Uranium North Resources Corp. – South Baker/Dubawnt Property

The 2008 Annual Report satisfactorily addressed some of the requirements of Part B, Item 2 of the current water licence # 2BE-DUB0812. However, it was noted that the following information was not provided in the 2008 Annual Report

Part B: Item 2, (a) of the water license requires a summary report of water use and waste disposal activities and, as per Item 2 (b), a list of unauthorized discharges and a summary of follow-up actions taken. The report does not reference any activities such as water use, sewage disposal, drill waste management and associated water use, solid and hazardous waste management and greywater management. No unauthorized discharges were reported in the report. It should be clearly stated in the report as to whether or not there have been any unauthorized discharges.

Part B: Item 2, (e) requires a summary of all information requested and results of the Monitoring Program. According to Part J, Item 8 the licensee shall include in the Annual Report all data, monitoring results and information required by Part J of the water license. For example there is no record of measurements/record in cubic metres of the daily quantities of water utilized for camp, drilling and other purposes; GPS co-ordinates of all locations where sources of water are utilized for all purposes; GPS co-ordinates of all locations where wastes associated with camp operations and drilling operations are deposited.

Part B: Item 2, (d) requires a description of all progressive and or final reclamation work undertaken, including photographic records of site conditions before, during and after completion of operations. There is no information provided in respect to abandonment and restoration or temporary closing. There are no photos or GPS coordinates included in the 2008 Annual Report of any of the drill sites indicating reclamation at any of these sites.



Recommendations

- 1) Uranium North should provide the information referenced above to the NWB and an INAC Inspector by July 30, 2009.
- 2) This information has been forwarded to INAC's Field Operations Unit

Cc: Kevin Buck – Water Resources Manager, INAC