

NWB Annual Report

Year being reported: 2007 ▼

License No: 2BE-EDE-0608

Issued Date: June 7, 2006

Expiry Date:

Project Name: EDEHON LAKE, KIVALLIQ REGION - KEEWATIN PROJECT

Licensee: TRI ORIGIN EXPLORATION LTD

Mailing Address: 125 DON HILLOCK DRIVE, UNIT 18
AURORA, ON
L4G 0H8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Diamond drilling of 7 holes, totalling 536m.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	EDEHON LAKE, LOCAL PONDS AT DRILL SITES	
Water Quantity:	100 cu m	Quantity Allowable Domestic (cu.m)
	< 20 cu m	Actual Quantity Used Domestic (cu.m)
	< 85 cu m	Quantity Allowable Drilling (cu.m)
	< 20 cu m	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
☒ Sewage
☒ Drill Waste
☒ Greywater
☐ Hazardous
☐ Other:

Additional Details:

EDEHON LAKE CAMP SITE MANAGED BY HENIK LAKE ADVENTURES LTD,
FROM ARVIAT. WATER LICENCE NO 3BC-EDE-0611, LAND USE PERMIT NO
N2006J0030

Nunavut Water
Board
JUL 18 2011
Public Registry

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Select

Additional Details:

Revisions to the Abandonment and Restoration Plan

Select

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

DRILL SITES RESTORED TO PRE-DRILL CONDITION. DECANT DRILL WATER
FILTERED THROUGH SANDS IN NATURAL DEPRESSIONS. FOREIGN
MATERIAL REMOVED FROM SITE

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below

Additional Details:

EL-07-1 and EL-07-2 6715102, 595017
EL-07-3 6709272, 588580
EL-07-4 and EL-07-5 6705949, 594389; EL-07-6 6711900, 587915

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider**Date Submitted:****Submitted/Prepared by:****Contact Information:****Tel:** **Fax:** **email:**