WATER LICENCE INSPECTION FORM	Original Follow-Up Report
-------------------------------	---------------------------

Sabina Gold and S	Cobine Cold and Cilver				Licensee Representative				
Sabina Gold and Silver				Cheryl Wray, Merle Keefe					
Licence No. / Expiry			The state of the s	Representative's Title					
2BE-GEO1015 Land / Other Authorizations				Environmental Superintendent Land / Other Authorizations					
tand / Other Authorizations			Land /	Other Authorizat	ions				
Date of Inspection	Western And		Inspect	or					
11/07/2014				Eva Paul					
Activities Inspected		Market 1							
	Drilling	ater Discha		Construction Other: Spills	□ Reclamation	□ Fuel Stora	ge		
Noads/Hadiling	J Other: W	ater Dischar	ige Z	Other. Spins					
Conditions: A - Ac	ceptable		C - Concern U - Unacc	eptable	NA – Not Applicable	NI – Not In	spected		
Water Use	Condition	Comment	Site Conditions		Comment Haz/Mat Manage	ement Condition	Comment		
Intake/Screen	NA		Water Management Structure	es A	Storage	Α	January Comment		
Flow Measure. Device	NA		Culverts / Bridges	NA	Spills	Α	3		
Source: George Lake	Α		Drainage	A	Spill Plan	Α			
Water Use:	NA		Erosion / Sediment	С					
Recirculation (y /n)	NA		Mitigation Measures	Α	Administrative	Charles Sign			
			Reclamation Activities	Α	Records	Α			
			Materials Storage	Α	Reports	Α			
Waste Disposal			Signage	NI	Plans	Α			
Waste Water	А	1			Notifications	Α			
Solid Waste	Α	2	Monitoring		Other				
Hazardous Waste	Α		Sample Collection / Analys	is NA	Core Stacks	U			
*Th	e numbe	er in the co	omments field will correspon	d with specifi	c comments provided belo	ow.			
Samples taken by Inspec	tor:		Location(s): George Lake	at the water in	ntake.				
⊠ Yes ☐ No									
SECTION 1	Comme	nts (s.1)	Non-Compliance	with Act or L	icence (s.2) 🔀 Ac	tion Required	(s.3)		
George Camp is not curr	ently op	en, nor is	drilling occurring under this	licence.					
1 The greywater line at	George	was impr	oved since 2013. A small be	rm has been r	out in place to mitigate th				
		was iiiipi	oved since 2015. A sinali be	illi lias beeli k	out in place to mitigate th	a impact of ava			
outflow on the nearby pond. 2. Minimal waste is seen on-site at George, Pallets of crushed barrels are awaiting backbaul.							ywater		
 Minimal waste is seen on-site at George. Pallets of crushed barrels are awaiting backhaul. Spill 12-334 will be closed with the Spill Line as a result of this inspection. More information is required with respect to spill 12- 							ywater		
3. Spill 12-334 will be cl	osed wit	h the Spil	Line as a result of this inspe	ection. More i	backhaul. information is required wi	th respect to s	pill 12-		
3. Spill 12-334 will be cl 204 before it can be i	osed wit	h the Spill d. Sabina	Line as a result of this inspe is to determine the actual co	ection. More i pordinates of	backhaul. information is required wi	th respect to s	pill 12-		
3. Spill 12-334 will be cl 204 before it can be i were in camp, howev	osed wit inspected ver, the r	h the Spill d. Sabina eport indi	Line as a result of this inspe is to determine the actual co cates the spill was on a lake	ection. More i cordinates of	backhaul. information is required wi the occurrence; those list	th respect to s ed on the spill	pill 12- report		
3. Spill 12-334 will be cl 204 before it can be i were in camp, howev4. It was noted during t	osed wit inspected er, the r he inspe	h the Spill d. Sabina eport indi ction that	I Line as a result of this inspe is to determine the actual co cates the spill was on a lake the old core stacks are very	ection. More incordinates of close to the w	backhaul. information is required wi the occurrence; those list vater. The licence require	th respect to s ed on the spill	pill 12- report		
 3. Spill 12-334 will be cl 204 before it can be it were in camp, howeve 4. It was noted during that least 31 m from the 	osed wit inspected er, the r he inspe- e high w	h the Spill d. Sabina eport indi ction that ater mark	I Line as a result of this insperies to determine the actual concates the spill was on a lake the old core stacks are very of any water body. It was a	ection. More incordinates of a close to the walso noted, how	backhaul. information is required wi the occurrence; those list vater. The licence require wever, that operating ma	th respect to sed on the spill state to the spill state to the spill state that core be schinery in that	pill 12- report		
3. Spill 12-334 will be cl 204 before it can be i were in camp, howeve 4. It was noted during t at least 31 m from th resulted in rutting an	osed wit inspected ver, the r he inspe e high w d gougin	h the Spill d. Sabina eport indi ction that ater mark g of the v	I Line as a result of this insperies to determine the actual control is to determine the actual control is to determine the actual control is to determine the spill was on a lake the old core stacks are very to fany water body. It was a degetation, so care will be reconstituted.	ection. More in coordinates of close to the walso noted, how quired when u	backhaul. information is required wi the occurrence; those list vater. The licence require wever, that operating ma indertaking this operation	th respect to sed on the spill as that core be chinery in that	pill 12- report stored area		
 3. Spill 12-334 will be cl 204 before it can be it were in camp, however. 4. It was noted during that least 31 m from the resulted in rutting an an	osed wit inspected yer, the r he inspe e high w d gougin	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s)	I Line as a result of this insperies to determine the actual control is to determine the actual control is to determine the actual control is to determine the spill was on a lake the old core stacks are very of any water body. It was a degetation, so care will be recompliance. Non-Compliance	ection. More in coordinates of close to the walso noted, how quired when u	backhaul. information is required with the occurrence; those list water. The licence require wever, that operating manufertaking this operation icence (s.2)	th respect to sed on the spill as that core be chinery in that n.	pill 12- report stored area		
 Spill 12-334 will be cl 204 before it can be it were in camp, however. It was noted during that least 31 m from that resulted in rutting an SECTION 2 	osed with inspected ver, the rehe inspected high with dispersion of the comments of the commen	h the Spill d. Sabina eport indi ction that ater mark g of the v nts (s) store drill	I Line as a result of this inspectis to determine the actual control is to determine the spill was on a lake the old core stacks are very to fany water body. It was a degetation, so care will be recompliance with the apputation of the actual interest and the stack of the spill is to determine the stack of the spill is to determine the stack of the stack	ection. More in coordinates of close to the walso noted, how quired when under with Act or Lartenant under	backhaul. Information is required with the occurrence; those list vater. The licence require wever, that operating main dertaking this operation icence (s.2) Activities Activities of Activities Activities Activities and Activities	th respect to sed on the spill as that core be chinery in that in.	pill 12- report stored area (s.3)		
 Spill 12-334 will be cl 204 before it can be it were in camp, howeved. It was noted during that least 31 m from that resulted in rutting an a section 2 Part I item 12: The Licens at least thirty one (31) m 	osed with inspected yer, the rehe inspected high will gought. Commensee may etres ab	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or	I Line as a result of this inspection to determine the actual control is to determine the spection of any water body. It was a degetation, so care will be recompliance with the appurationary high water mark of a	ection. More in coordinates of close to the walso noted, how quired when under with Act or Lartenant under	backhaul. Information is required with the occurrence; those list vater. The licence require wever, that operating main dertaking this operation icence (s.2) Activities Activities of Activities Activities Activities and Activities	th respect to sed on the spill as that core be chinery in that in.	pill 12- report stored area (s.3)		
 Spill 12-334 will be cl 204 before it can be it were in camp, howeved. It was noted during that least 31 m from the resulted in rutting an an	osed with inspected ver, the rehe inspected high will gought to the comment of th	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa	I Line as a result of this inspective to determine the actual control is to determine the spill was on a lake the old core stacks are very to of any water body. It was a degetation, so care will be recommended by the appurationary high water mark of a facts are created.	ection. More in coordinates of close to the walso noted, how quired when under the coordinate with Act or Lartenant under ny adjacent was coordinates.	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating maindertaking this operation icence (s.2) Activates body, where any directions in an appropriate vater body.	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a second control of the second control of t	pill 12- report stored area s.3) cation water		
3. Spill 12-334 will be cl 204 before it can be it were in camp, howeve 4. It was noted during that least 31 m from that resulted in rutting an SECTION 2 Part I item 12: The Licens at least thirty one (31) m body is not possible and SECTION 3	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa nts (s)	I Line as a result of this insperies to determine the actual control is to determine the spill was on a lake the old core stacks are very to fany water body. It was a degetation, so care will be recommended by the appurationary high water mark of a dects are created. Non-Compliance	ection. More in coordinates of close to the walso noted, how quired when under the coordinate with Act or Lartenant under my adjacent walso with Act or Lartenant walso was a second was a sec	backhaul. Information is required with occurrence; those list water. The licence require wever, that operating manndertaking this operation icence (s.2) Activates body, where any direction icence (s) Activates body, where any direction icence (s)	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and locat flow into a stion Required (tion Required	pill 12- report stored area s.3) cation water		
 3. Spill 12-334 will be cl 204 before it can be it were in camp, however. 4. It was noted during that least 31 m from that resulted in rutting an section 2. Part I item 12: The License at least thirty one (31) m body is not possible and section 3. Please provide more. 	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this inspection to determine the actual control of the spill was on a lake the old core stacks are very to fany water body. It was a segetation, so care will be recovered by the appurationary high water mark of a facts are created. Non-Compliance Non-Compliance Non-Compliance	ection. More is coordinates of close to the value of the	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
 3. Spill 12-334 will be cl 204 before it can be it were in camp, however. 4. It was noted during that least 31 m from that resulted in rutting an section 2. Part I item 12: The License at least thirty one (31) m body is not possible and section 3. Please provide more. 	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this insperies to determine the actual control is to determine the spill was on a lake the old core stacks are very to fany water body. It was a degetation, so care will be recommended by the appurationary high water mark of a dects are created. Non-Compliance	ection. More is coordinates of close to the value of the	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
 3. Spill 12-334 will be cl 204 before it can be it were in camp, however. 4. It was noted during that least 31 m from that resulted in rutting an section 2. Part I item 12: The License at least thirty one (31) m body is not possible and section 3. Please provide more. 	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this inspection to determine the actual control of the spill was on a lake the old core stacks are very to fany water body. It was a segetation, so care will be recovered by the appurationary high water mark of a facts are created. Non-Compliance Non-Compliance Non-Compliance	ection. More is coordinates of close to the value of the	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
3. Spill 12-334 will be cl 204 before it can be i were in camp, howeve 4. It was noted during t at least 31 m from th resulted in rutting an SECTION 2 Part I item 12: The Licens at least thirty one (31) m body is not possible and SECTION 3 Please provide more A plan and a timeline	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this inspection to determine the actual control of the spill was on a lake the old core stacks are very to fany water body. It was a segetation, so care will be recovered by the appurationary high water mark of a facts are created. Non-Compliance Non-Compliance Non-Compliance	ection. More is coordinates of close to the value of the	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
 3. Spill 12-334 will be cl 204 before it can be it were in camp, however. 4. It was noted during that least 31 m from that resulted in rutting an section 2. Part I item 12: The License at least thirty one (31) m body is not possible and section 3. Please provide more. 	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this insperies to determine the actual contents the spill was on a lake the old core stacks are very to fany water body. It was a segetation, so care will be recommended by the appurationary high water mark of a facts are created. Non-Compliance will be recommended by the appurationary high water mark of a facts are created. Non-Compliance will 12-204 as the spill file can be prepared and subtractions.	ection. More is coordinates of close to the value of the	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
3. Spill 12-334 will be cl 204 before it can be is were in camp, howeve 4. It was noted during to at least 31 m from the resulted in rutting an section 2 Part I item 12: The Licens at least thirty one (31) m body is not possible and section 3 Please provide more A plan and a timeline section of the provide more and the plan and a timeline section of the provide more and the plan and a timeline section of the plan and a timeline se	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this insperies to determine the actual contents the spill was on a lake the old core stacks are very to fany water body. It was a segetation, so care will be recommended by the appurationary high water mark of a facts are created. Non-Compliance will be recommended by the appurationary high water mark of a facts are created. Non-Compliance will 12-204 as the spill file can be prepared and subtractions.	ection. More in coordinates of coordinates of close to the walso noted, how quired when use with Act or Lintenant under my adjacent was with Act or Lintenant under the closed mitted to the	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
3. Spill 12-334 will be cl 204 before it can be i were in camp, howeve 4. It was noted during t at least 31 m from th resulted in rutting an SECTION 2 Part I item 12: The Licens at least thirty one (31) m body is not possible and SECTION 3 Please provide more A plan and a timeline	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	is to determine the actual control is to determine the spill was on a lake the old core stacks are very to of any water body. It was a degetation, so care will be reconstructed by the apputationary high water mark of a dects are created. Non-Compliance ill 12-204 as the spill file can regist to be prepared and subsequently in the control is to be prepared and subsequently in the control is to be prepared and subsequently in the control is to be prepared and subsequently in the control is to be prepared and subsequently in the control is to be prepared and subsequently in the control is to determine the control	ection. More is coordinates of close to the value of the	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
3. Spill 12-334 will be cl 204 before it can be is were in camp, howeve 4. It was noted during to at least 31 m from the resulted in rutting an SECTION 2 Part I item 12: The Licens at least thirty one (31) m body is not possible and SECTION 3 Please provide more A plan and a timeline Licensee or Representative Licensee or Representative Signature	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	is to determine the actual control is to determine	cction. More is coordinates of close to the value of close to the value of close to the value of the value of the value of the close of the value of the close of the value of the close of the value of	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
3. Spill 12-334 will be cl 204 before it can be is were in camp, howeve 4. It was noted during to at least 31 m from the resulted in rutting an section 2 Part I item 12: The Licens at least thirty one (31) m body is not possible and section 3 Please provide more A plan and a timeline section of the provide more and the plan and a timeline section of the provide more and the plan and a timeline section of the plan and a timeline se	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this insperies to determine the actual contents the spill was on a lake the old core stacks are very to of any water body. It was a segetation, so care will be recovered by the appurationary high water mark of a facts are created. Non-Compliance will 12-204 as the spill file can be prepared and subsequently in the prepared and subsequentl	close to the walso noted, how a with Act or Lartenant under my adjacent was with Act or Lartenant under the closed mitted to the moter of the closed mitted to the mature.	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
3. Spill 12-334 will be cl 204 before it can be is were in camp, howeve 4. It was noted during to at least 31 m from the resulted in rutting an SECTION 2 Part I item 12: The Licens at least thirty one (31) m body is not possible and SECTION 3 Please provide more A plan and a timeline Licensee or Representative Licensee or Representative Signature	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with t	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this insperies to determine the actual contents the spill was on a lake the old core stacks are very to of any water body. It was a segetation, so care will be recovered by the appurationary high water mark of a facts are created. Non-Compliance will 12-204 as the spill file can be prepared and subsequently in the prepared and subsequentl	cction. More is coordinates of close to the value of close to the value of close to the value of the value of the value of the close of the value of the close of the value of the close of the value of	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		
3. Spill 12-334 will be cl 204 before it can be is were in camp, howeve 4. It was noted during that least 31 m from that resulted in rutting an SECTION 2 Part I item 12: The License at least thirty one (31) m body is not possible and SECTION 3 Please provide more A plan and a timeline Licensee or Representative Licensee or Representative Signature Date	osed with inspected yer, the report of the inspected high with dispersion of the inspected high with the inspected high with the inspected high with the information of the information	h the Spill d. Sabina eport indi ction that ater mark ag of the v nts (s) store drill ove the or ional impa ion on spi	I Line as a result of this insperies to determine the actual of cates the spill was on a lake the old core stacks are very of any water body. It was a regetation, so care will be recommended by the appurationary high water mark of a facts are created. Non-Compliance will be recommended by the appurationary high water mark of a facts are created. Non-Compliance will 12-204 as the spill file can re is to be prepared and subsequently be appurated by the spill file can re is to be prepared and subsequently be appurated by the spill file can be appurated by the spill file	close to the walso noted, how a with Act or Lartenant under my adjacent was with Act or Lartenant under the closed mitted to the moter of the closed mitted to the mature.	backhaul. Information is required with the occurrence; those list water. The licence require wever, that operating mandertaking this operation icence (s.2) Activater body, where any direction was because it in the control of the c	th respect to sed on the spill as that core be chinery in that in. tion Required (manner and logect flow into a section Required (seen conducted.	pill 12- report stored area s.3) cation water		

