


WATER LICENCE INSPECTION FORM

\boxtimes	Original	
	Follow-Up	Report

Licensee				Licensee Representative							
Sabina Gold and S	N/A Representa	N/A Representative's Title									
2BE-GEO1520 and 2BE-GOO1520 -											
Land / Other Authorizations Land / Other Authorizations											
Date of Inspection Inspector											
17/07/2015 Eva Paul											
Activities Inspected											
☐ Roads/Hauling						☐ Construction ☐ Reclamation ☐ Fuel Storage ☐ Other:					
Conditions: A - Acceptable C - Concern U - Unacceptable NA – Not Applicable NI – Not Insp								spected			
Water Use	Condition Co	Site Conditions		Condition	Comment	Haz/Mat Manager	nent Condition	Comment			
Intake/Screen	NA	Water Manageme	nt Structures	С	1	Storage	А				
Flow Measure. Device	NA	Culverts / Bridge	!S	Α		Spills	А				
Source:	NA	Drainage		Α		Spill Plan	NI				
Water Use:	NA	Erosion / Sedime	ent	С	2						
Recirculation (y /n)	NA Mitigation Measures		ures			Administrative					
		Reclamation Act	ivities	NI		Records	Α				
		Materials Storag	e	Α		Reports	А				
Waste Disposal		Signage	Signage			Plans	А				
Waste Water	А					Notifications	А				
Solid Waste	А	Monitoring				Other					
Hazardous Waste	А	Sample Collection	n / Analysis	Α							
*Th	e number in	n the comments field will	correspond v	vith spec	ific comr	nents provided belov	v.				
Samples taken by Inspec	tor:	Location(s):									
Yes No											
SECTION 1	Comments	(s.1) Non-C	ompliance w	ith Act o	r Licence	(s) \times Act i	ion Required	(s.2)			
I conducted a brief inspe			-		-		•				
As such, no water was being used and no waste being deposited. Nothing of concern was noted at Goose Camp. Two items at											
George were noted:											
1. Collapsible berms containing fuel drums had filters installed, however, in several cases the filters are installed on a high corner											
of the berm and water was pooling in the lower corners rather than being drained and filtered.											
2. The fuel storage pad is showing significant erosion/slumping in some places. As this pad appears to be built in a marshy area, these slumps result in a spread of material and sediment into the wetland areas.											
SECTION 2	Comments	Non-C	☐ Non-Compliance with Act or Licence ☐ Action Required								
1. Please ensure that r	monitoring f	requency is sufficient to	prevent bern	ns from c	vertopp	ing.					
2. Steps should be taken to repair the erosion and slumping of materials from the fuel storage pad at George Camp into the											
wetlands below. Ple	ease confirm	n with the inspector by S	eptember 30	when th	is work o	an be carried out.					
Licensee or Representative				Inspector's Name							
-				Eva Paul							
Signature				Signature							
_											
Date	Date										
- 26/07/2015											
Office Use Only: Follow-up report to be issued by Inspector Yes No											

Att: Photo Log





South East side of the fuel storage pad: slumping and erosion is visible off the side, deposited into the wetland below.

