

NWB Annual Report

Year being reported: 2006 ▼

License No: 2BE-GEO0210

Issued Date: July 3, 2002

Expiry Date: December 31, 2010

Project Name: George Lake Camp

Licensee: Dundee Precious Metals

Mailing Address: Suite 3060, Royal Bank Plaza
200 Bay Street
Toronto, ON M5J 2J1

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

As above.

General Background Information on the Project (*optional):

Mineral exploration including diamond drilling.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	George Lake	
Water Quantity:	100	Quantity Allowable Domestic (cu.m/day)
	0	Actual Quantity Used Domestic (cu.m/day)
		Quantity Allowable Drilling (cu.m)
	40	Total Quantity Used Drilling (cu.m/day)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☒ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

Up to a combined 100 m3/day allowable for domestic use and drilling/trenching.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: _____ (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

On March 29th 4 drums of Jet-A fuel were punctured by the Loader while they were being dug out of the snow. Drums were moved to the gravel airstrip and burnt, while all visible fuel spilt was collected up with absorbing mat and also burnt. Further details (report number, etc.) could not be readily located. Will continue searching and forward information if found.

On April 23rd 40 litres of P-50 diesel leaked from a fuel tank on the D-6 Cat dozer. Fuel was collected with absorbing mat and burnt. Further details (report number, etc.) could not be readily located. Will continue searching and forward information if found.

Report #06-215. On May 28th one drum of P-50 diesel burst when it dropped from from a helicopter while it was being transported to the drill. Cause was determined to be due to a mismatch of the lanyard to the long line. Drum landed adjacent to the esker strip. Drum and fuel was burnt on the esker strip. Phone contact made with Craig Broom of Environment Canada.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Waste materials stored at the George Lake Camp were organized for removal during next years mobilization of consumables. The old kitchen complex was demolished.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below



Additional Details:

No domestic water use occurred at George Lake in 2006.

To the best of my knowledge, coordinates were not obtained for water sources used for drilling at George Lake. The project manager at the time is no longer with Dundee Precious Metals.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below ▼

Additional Details:

65°55'02" N, 107°27'37" W - Drill cuttings sump (cuttings captured at rig with megabag system)

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

No inspection conducted by INAC in 2006.

Any additional comments or information for the Board to consider

Date Submitted:	March 31, 2008
Submitted/Prepared by:	Dan Russell, P.Geo.
Contact Information:	Tel: 416-365-2841
	Fax: 416-365-9080
	email: drussell@dundeprecious.com (preferred method)