

NWB Annual Report

Year being reported: 2006 ▼

License No: 2BE-GOO0510

Issued Date: March 11, 2005

Expiry Date: March 31, 2010

Project Name:

Licensee:

Mailing Address:

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

▼ ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	<input type="text" value="Goose Lake and unnamed lakes in vicinity of drilling"/>	
Water Quantity:	<input type="text" value="130"/>	Quantity Allowable Domestic (cu.m)
	<input type="text" value="6.4"/>	Actual Quantity Used Domestic (cu.m)
	<input type="text" value=""/>	Quantity Allowable Drilling (cu.m)
	<input type="text" value="114.5"/>	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☒ Sewage
- ☒ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: 06-289 (as reported to the Spill Hot-line)

Date of Spill: July 17, 2006

Date of Notification to an Inspector: July 18, 2006

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

At approximately 0730, 2 miles NW of Goose Lake camp, a mismatch between the long line and bell hook attached to the helicopter occurred, releasing 3 drums of P50 from an altitude of approximately 500 feet. Fuel was burned off, residue absorbed with enviromat and the drums returned to Goose Lake camp. No further environmental impacts were observed.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Work was continued to keep the camp and the drill sites clean. The original drill cuttings dump site was cleaned of all plastics and rubbish. All empty fuel drums, incinerator waste and other garbage were flown out of the camp, early in 2006, as part the backhaul, and either returned to the original vendors (fuel drums) or sent to a certified waste disposal site. A drum crusher was purchased in 2006 and will be utilized to crush all used drums for backhaul and disposal.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below ▼

Additional Details:

65°32'42" N, 106°25'29" W - domestic water source for camp
65°32'39" N, 106°25'23" W - water source for drilling activities at Goose Lake

To the best of my knowledge, coordinates were not obtained for water sources used for drilling at Boot Lake and Boulder Pond. The project manager at the time is no longer with Dundee Precious Metals.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below ▼

Additional Details:

65°32'37" N, 106°25'36" W - Incinerator
 65°32'39" N, 106°25'39" W - Greywater sump
 65°32'30" N, 106°25'35" W - Drill cuttings sump (cuttings captured at rig with megabag system)

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

No inspection conducted by INAC in 2006.

Any additional comments or information for the Board to consider

Date Submitted:

March 31, 2008

Submitted/Prepared by:

Dan Russell, P.Geo.

Contact Information:

Tel: 416-365-2841

Fax: 416-365-9080

email: drussell@dundeprecious.com (preferred method)