



Indian and Northern
Affairs Canada
www.inac.gc.ca

Affaires indiennes
et du Nord Canada
www.ainc.gc.ca

DIAND - INAC Operations
Box 129
Rankin Inlet, NU
XOC OGO

Your file - Votre référence

Our file - Notre référence

Dec. 3, 2010

Aura Silver Resources Inc.
341 Main St. North,
Suite 206
Brampton, Ont.
L6X 3C7

Dear Sir/Madam,

Re: Land Use Permit N2010C0008
Drilling
Baker Lake Area

An inspection of site utilized under the authorization of Land Use Permit N2010C0008 was conducted by Land Use Inspector, Henry Kablalik on July 22, 2010.

Enclosed is a copy of the Inspection Report for your attention and retention.

Should you have questions, please do not hesitate to call me at (867) 645-2831 or failing that, you may contact Mr. Peter Kusugak, Manager in Iqaluit at (867) 975-4290.

Yours truly,


Henry Kablalik
Resource Management Officer IV
Kivalliq Region

cc: Peter Kusugak, Manager of Operations
John Craig, Land Administrator Specialist

Canada

Printed on recycled paper - Imprimé sur papier recyclé

2/3

ENVIRONMENTAL INSPECTION REPORT

Date: July 22/10

Permittee: (complete name and address)

Aura Silver Resources Inc. 341 Main St.North, Suite 206 Brampton, Ont. L6Y-3C7

Land Use Permit No. 1	<u>N20PC0008</u>	Permit Expiry Date	<u>May 8, 2012</u>	Last Previous Inspection	<u>N/A</u>
Quarrying Permit No.					
Contractor:	Subcontractor:				

Location(s) Inspected:

64°38'08.0"N 96°19'08.0"W Note: 3 drums too close to the water. Drill near quarry #8

Current Stage of Operation:

On-Going

Program Modifications Approved:

Condition of Operation "A"-Acceptable "U"-Unacceptable "N/A"-Not Applicable

	Operating Condition	Aspect Inspected			
A	Location as Permitted	<u>A</u>			
B	Timing as Permitted	<u>A</u>			
	Equipment as Approved	<u>A</u>			
D	Methods & Techniques	<u>NA</u>			
E	Facilities	<u>A</u>			
F	Erosion	<u>A</u>			
G	Chemicals, Waste	<u>A</u>			
H	Wildlife & Fisheries Habitat	<u>A</u>			
I	Ecological Resource	<u>A</u>			
K	Fuel Storage	<u>U</u>			<u>31(.) (X) - #47</u>
L	Brush Disposal	<u>NA</u>			
M	Matters Not Inconsistent	<u>A</u>			
N	Water Engineering	<u>NA</u>			
O	Water Supply	<u>NA</u>			
P	Restoration	<u>NA</u>			
Q	Quarrying Methods	<u>NA</u>			
R	Sections 12 to 19 T.L.U.R.	<u>NA</u>			
S					
T					

Surveillance Network Program

Explanatory Remarks (attach page 2, if required):

There were 3 (45gal) drums too close to the water. No one at the site at the time to talk to.Page 2 attached ☐ Yes ☐ No

Representative's Signature

RMO Initials

Inspector's Signature

Representative's Title

District Mgr. Initials

To: Paul Pitman
PWP Consulting
Brampton, Ont.

Re: N2010C0008 - Aura Silver Resources Inc.

Here is a copy of the 2010 inspection report
EYI.

If you have any questions please do not
hesitate to call me at 867-645-2831 or email
me at any time.

Henry

cc. Kevin Robertson - RMO IV 19alrit