

# **Attachment B**


## **Photolog**



Gartner Lee


Attachment B  
- PHOTOGRAPHS -

PHOTOGRAPH 1



Typical drainage channel with moderate flow at time of site visit. This is the outlet of Upper Sunken Lake, looking northwest towards Upper Sunken Lake.

PHOTOGRAPH 2



This is a typical inflow and outflow of the lakes and rivers at time of site visit. This photo typifies Mara Inflow #2, looking towards the southeast.


Attachment B  
- PHOTOGRAPHS -

PHOTOGRAPH 3



Mara Inflow #1 looking east. Very little flow at time of visit.


PHOTOGRAPH 4



Upper Sunke Lake, looking south. Jeff Kadlun graciously points to the exact sample location.


- PHOTOGRAPHS -

PHOTOGRAPH 5



Mara River (downstream sample location) south side looking downstream.

PHOTOGRAPH 6



Camp Lake looking due north looking away from camp. Sample location at bottom left.