

Photograph 1: Aerial survey of former Heequo camp location. Six former tent frame locations, latrine site, former fuel cache and helicopter pad area are identifiable in this view.





Photograph 2: Former latrine location; water has accumulated in the depression.



Photograph 3: Former sumps have not been restored properly.





Photograph 4: Burn site has not been cleaned up; coals and metal debris remain.



Photograph 5: View of noncombustible material and nails left in the burn area.





Photograph 5: Closer view of former tent frame area. Vegetation appears to be recovering.