



2BE-IZO0712 Inspection of July 3rd, 2012

Photos from Inspection



Figure 1. Water source in use for Drill 1466. Screen visible on the intake.



Figure 2. Waste from the incinerator, showing items which are not to be burned.



Figure 3. New 11,000 L tanks.



Figure 4. Fuel Transfer Station. Nozzles contained to avoid drips; spill kit visible.



Figure 5. Drill 1493, with drill waste spilling down the side of the hill.



Figure 6. Drill 1493 setup - showing pallets sitting unused, while fuel and salts have no containment.



Figure 7. Drums held on timbers, sloped off the hill at a downward angle.



Figure 8. Salt stored without containment.



Figure 9. Hood helicopter refueling area - no secondary containment.



Figure 10. Leaking barrel at Hood.



Figure 11. Good use of containment for waste products in camp.



Figure 12. Absorbent beneath jerry cans as preventative measure. Waste batteries contained in suitable bin.



Figure 13. Ashes remaining after burning of camp structure at Hood.



Figure 14. Core rack possibly <30 m from high water mark.