



## Water Licence Inspection Report

☐ Original  
☐ Follow-Up Report

Authorization	Representative
<b>MMG (Hood Camp)</b>	<b>Sarah Hasek</b>
Authorization No. / Expiry	Representative's Title
86I2-1 (2BE-IZO2328)	<b>Tenement Officer</b>
Other Authorization/s	
N2024C0022	
Activities Inspected	
<input checked="" type="checkbox"/> Camp, Commercial <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input checked="" type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Winter Hauling <input type="checkbox"/> Camp, Private <input type="checkbox"/> Other <small>Click or tap here to enter text.</small>	

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
	Condition		Observation No.		
31 (1)(a) Location and Area	A				
31 (1)(b) Time					
31 (1)(c) Equipment					
31 (1)(d) Methods and Techniques					
31 (1)(e) Type location, capacity and operation of facility	C		#9, #10		
31 (1)(f) Control or prevent of flooding, erosion, and subsidence of Land	A				
31 (1)(g) Use, storage, handling and disposal of chemical or toxic materials	A				
31 (1)(h) Wildlife and fisheries habitat					
31 (1)(i) Objects and places of recreation, scenic and ecological value					
31 (1)(k) Petroleum fuel storage	NA				
31 (1)(m) Matters not inconsistent with the regulations					

\*refers to specific terms and conditions found in the permit/lease in question.

### Section 1 Comments

On August 1, 2024, I, Isaiah James Bolt, Inspector with the Crown Indigenous Relations and Northern Affairs Canada (CIRNAC), writer of this report, Along with fellow inspector Jonathan Mesher, of CIRNAC, conducted an on-site visit of Hood Camp (86I2-1)(2BE-IZO0712) to ensure compliance of their lease and water license.

Based on the last inspection from Eva Paul in 2017, it seems 3 cabins along the shore have been removed from site, along with the trash barrels and debris around the cabins. No concerns noted.

1. Inspectors arrived on site at 5:00PM on August 1<sup>st</sup>, 2024.
2. Aerial Photos were taken (Photo # 1 and #2)
3. Drill rods were present on site in a stacked manner. (Photo #3)
4. A pile of lumber was observed on site (Photo # 4)
5. Roofing material was stacked on top of a wooden wall in the tundra (Photo #5)
6. Ply wood debris observed on the ground behind the core shack. (Photo #6)
7. A small abandoned shack was observed on site with no roof and no door. There was nothing in the shack that would attract wildlife. Reclamation of this building is required. (Photo #7)
8. Core boxes were observed on the north side of the core shack. No issues noted. (Photo #8)
9. The door of the core shack was damaged and open. Signs of a bear breaking in were observed as the door was broken, scratched and chewed up (Photo #9)



10. Signs of a bear staying in the core shack were observed. Debris and mess were observed all around the floor (Photo #10 and #11)
11. A steel frame was observed close to the shore of the lake (Photo #12)
- No other concerns were noted at this site. No fuel or contaminants present on site.

**Section 2 Non-Compliance with** Choose an item.

-In regards to comment #3,#4, #5, #6, #7 and #11: Part I, Item 5 of the issued water license states: "The licensee shall remove from the site, all infrastructure and site materials, including all fuel caches, drums, barrels, buildings and contents, docks, water intakes, pumps and lines, materials and equipment prior to the expiry of this license".

-In regards to comment #9 and #10: The building at Hood camp (core shack) should be repaired to deny entry of wildlife into the building.

**Section 3 Action Required**

-Remove all equipment related to the undertaking and restore the land back to its natural state. Information about the future plans of the core shack should be reported to the Inspector, (i.e.. demobilization, deconstruction).

-Ensure buildings that are housing core, are up to operational standards to deny entry of wildlife as per the Inspectors request.

**Section 4 Other**

Licensee or Representative	Inspector's Name
GREY NATION	Isaiah James Bolt
Signature	Signature
[Signature]	James Bolt
Date	Date
4 Oct 2024	2024/10/04

Office Use Only: Follow-up report to be issued by Inspector

☐ Yes ☐ No

PHOTO LOG

Date	Camera	Inspector	Authorization
2024 August 1	Olympus Tough TG-6	James Bolt	2BE-IZO2328
Photo Log # P8010727			





Photo 1



Description: Aerial View of Hood Camp. Core shack is the large building, core boxes, drill rods and an abandoned shack observed.

Photo Log # P8010729

Photo 2



Description: Aerial View #2, showing the removal of 3 cabins that used to be where the arrow on the image is pointing.





Photo Log # P8010732

Photo 3



Description: Stack of drill rod present on site.

Photo Log #P8010733

Photo 4



Description: Stack of Lumber present on site.





Photo Log #P8010734

Photo 5



Description: Metal sheet roofing placed on top of a wooden wall in the tundra.

Photo Log # P8010736

Photo 6



Description: ply wood debris behind the core shack (silver)





Photo Log # P8010739

Photo 7



Description: Stacked drill rods, abandoned shack and some core boxes.

Photo Log # P8010750

Photo 8



Description: Core boxes outside, core shack (Silver) shown with an open door





Photo Log # P8010745

Photo 9



Description: Core shack door as seen from inside. The door is heavily damaged and unable to close.

Photo Log # P8010747

Photo 10



Description: Active tank farm, 6 tanks





Photo Log # P8010746

Photo 11



Description: Debris inside the core shack

Photo Log # P8010730

Photo 11



Description: A large steel frame on the tundra close to where old cabins were situated.