



2BE-KDP1722 Kahuna Camp Inspection Report

Emily McNie <emcnie@kodiakcoppercorp.com>

Wed, Nov 18, 2020 at 2:57 PM

To: "christine.wilson3@canada.ca" <christine.wilson3@canada.ca>, Licensing Department <licensing@nwb-oen.ca>

Cc: Andrew Berry <aberry@kodiakcoppercorp.com>

Hello Christine,

Kodiak Copper Corp. received your inspection report on November 4, 2020. The actions requested are outlined below.

The six open buckets are filled with sand and gravel that was collected from around the incinerator. There is likely some oil or hydrocarbon material in them, but in very small amounts. The buckets were originally dry and in a covered plywood box; however, the top of the plywood box was removed which allowed rainwater to collect in the buckets.

We have contacted Curly Construction to cover and remove the buckets from camp. Curly Construction will consolidate the buckets into one 45-gallon drum and stage the bucket at their shop until it can be placed on the sealift for authorized disposal in Southern Canada.

When Curly Construction is in camp collecting the buckets, they will secure the ripped secondary containment berm and photograph the revision. Due to the current freezing conditions and snow cover, the camp maintenance visit is planned for the spring.

If you require any additional information, please feel free to email me at emcnie@kodiakcoppercorp.com

Regards,

Emily McNie

Project Geologist

Kodiak Copper Corp. TSX.V.KDK

1020 - 800 West Pender Street

Vancouver, BC, V6C 2V6

Mobile: +1 604-603-0260

emcnie@kodiakcoppercorp.com

www.kodiakcoppercorp.com



2BE-KDP1722-Inspection Report Response-Kodiak-20201118.pdf

105K