

LAND USE PERMIT INSPECTION FORM

Permittee	Representative
Solstice Gold Corporation	Marty Tunney
Permit No. / Expiry	Representative's Title
N2018C0020	President
Other Authorizations/ Expiry	Project Name
2BE-KGP1823/ December 16 <sup>th</sup> , 2023	Kahuna Gold Project
Date of Inspection	Inspector
12/07/2019	RMO Wilson
Activities Inspected	
<input type="checkbox"/> Campsite <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage	
<input type="checkbox"/> Roads/hauling <input type="checkbox"/> :Other:	

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
Section:	Term No.	Condition	Observation No.		
31 (1)(a) Location and Area	--	A	--		
31 (1)(b) Time	13	C	1		
31 (1)(c) Equipment	--	--	--		
31(1)(b) Methods and Techniques	20, 22	U, A	1		
31 (1)(e) Type Location, Capacity and Operation of Facility	26	A	1		
31 (1)(f) Control or prevent of flooding, erosion, and subsidence of Land	---	---	---		
31 (1)(g) Use, Storage, Handling and Disposal of Chemical or Toxic Materials	--	--	--		
31 (1)(h) Wildlife and Fisheries Habitat	---	---	---		
31 (1)(k) Petroleum Fuel Storage	--	--	--		
31 (1)(m) Matters not Inconsistent with the Regulations	--	--	--		

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
An inspection of Solstice Gold Corporation's ('Solstice') Kahuna Gold Project was completed by Crown-Indigenous Relations and Northern Affairs Canada ('CIRNAC')'s, Resource Management Officers, Christine Wilson ('Inspector') and Jakob Voisey. The inspection was conducted to ensure compliance with applicable terms and conditions of land use permit no. N2018C0020.			
PRELIMINARY NOTES			
— A temporary fly camp has been established at N63° 4' 53", W91° 26' 4" (photo 1). Solstice had two staff working from the temporary camp at the time of inspection.			
OBSERVATIONS			
1. A total of five drill sites were inspected. The holes were drilled during the 2018 drilling campaign.			
Drill Site Name	Approximate Location	Observations	Actions Required
2019-04	N63° 4' 53", W91° 26' 4"	Isolated cuttings, collar still present, not capped, over 30m from water.	-Remove collar or cut and cap.
2019-03	N63° 4' 36", W91° 24' 55"	Isolated cuttings, collar cut off at the ground, over 30m from water.	None
2019-05	N63° 4' 19.93", W 91° 23' 36.8"	Small amount of garbage, collar still present, isolated cuttings, over 31m from water.	-Remove collar or cut and cap. -Remove garbage.
2019-02	Unknown	The drill site was never found.	N/A
2019-06	N63° 5' 46", W91° 22' 43"	Collar still present, isolated cuttings, hole is over 31m from water but cutting may be at 31m	-Remove collar or cut and cap. -Ensure cutting are over 31m from water.
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Regulations	<input type="checkbox"/> Action Required
Non-compliance or failures to comply related to the conditions of Land Use Permit no. N2018C0020;			
— Item 20: Failure to restore drill holes and disturbed areas to natural conditions immediately upon completion of the activity.			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input checked="" type="checkbox"/> Action Required
Solstice completed restoration of the drill site 2019-05 prior to the issuance of this report. Solstice plans to complete the restoration of drill site 2019-06 and 2019-04 this field season once aircraft and weather is favourable. Solstice will provide photographic evidence of the restoration of these two drills site to the Inspector, prior to Dec 1 <sup>st</sup> , 2020.			



Licensee or Representative	Inspector's Name
	RMO Wilson
Signature	Signature
	<i>Emailed</i>
Date	Date
	September 25th, 2020
Office Use Only: Follow-up report to be issued by Inspector <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	



Date	Camera	Inspector	Authorization
August 6 <sup>th</sup> , 2020	Sony DSC-HX50V Cyber Shot	RMO Wilson	N2018C0020
Photo Log		Location (NAD 83 DD MM SS.SS)	
Photo 1		N63° 03' 44.52", W91° 25' 40.00"	



Description:
Fly Camp





Photo Log

Location (NAD 83 DD MM SS.SS)

Photo 2

N 63° 4' 53.51", W 91° 26' 4.25"



Description:

Drill Site 2019-04, casing not cut and capped.





Photo Log

Location (NAD 83 DD MM SS.SS)

Photo 3

N 63° 4' 35.75", W 91° 24' 55.34"



Description:

Drill Site 2019-03





Photo Log

Location (NAD 83 DD MM SS.SS)

Photo 4

N 63° 4' 19.93", W 91° 23' 36.8"



Description:

Drill Site 2019-05, Casing still in ground





Photo Log

Location (NAD 83 DD MM SS.SS)

Photo 5

N 63° 4' 21.923", W 91° 23' 34.10"



Description:

Drill Site 2019-05, Garbage at site





Photo Log

Location (NAD 83 DD MM SS.SS)

Photo 6

N 63° 4' 21.209", W 91° 23' 39.59"



Description:

Drill Site 2019-06, Collar in ground and not capped.