



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 06-17-2015	REPORT TIME 20:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR		REPORT NUMBER -
B	OCCURRENCE DATE: MONTH – DAY – YEAR 06-17-2015	OCCURRENCE TIME 16:30	<input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) N2014C0001		WATER LICENCE NUMBER (IF APPLICABLE) 2BE-KIG1318		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION 7.4 km West of AREVA Kiggavik camp			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES 64 MINUTES 25 SECONDS 17.91		LONGITUDE DEGREES -97 MINUTES 48 SECONDS 17.18		
F	RESPONSIBLE PARTY OR VESSEL NAME AREVA Resources Canada Inc	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Box 9204 817 45th St. West Saskatoon, SK S7K 3X5			
G	ANY CONTRACTOR INVOLVED Boart Longyear	CONTRACTOR ADDRESS OR OFFICE LOCATION 4025-96 Avenue S.E. Calgary, AB T2C 4T7			
H	PRODUCT SPILLED Drill cuttings	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES Unknown		U.N. NUMBER N/A	
	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A		U.N. NUMBER N/A	
I	SPILL SOURCE Drill cuttings from drill hole	SPILL CAUSE Runoff caused mobilization		AREA OF CONTAMINATION IN SQUARE METRES 2000 square meters	
J	FACTORS AFFECTING SPILL OR RECOVERY N/A	DESCRIBE ANY ASSISTANCE REQUIRED N/A		HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT N/A	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS While the drillers were installing the casing, they were drilling through the overburden. During this operation, the overburden consisting of fine materials was washed down the hill into a small water body. This was further facilitated by the excess clean water hose washing the fine materials into the water body. Socks have been placed around the spill area containing the sediment near the drill. The excess clean water line was extended away from the affected area to reduce the further migration of fine material. A sump was installed at the drill hole to stop more fine material and water from washing down the hill. An additional sump was placed in the affected areas and used to pump the dirty water away from the small lake. The sumps are pumping the silty water to the discharge area which is contained and an acceptable distance from the small lake.				
L	REPORTED TO SPILL LINE BY Brad Pohler	POSITION SHEQ Supervisor	EMPLOYER AREVA	LOCATION CALLING FROM Kiggavik Camp	TELEPHONE 306-683-9562
M	ANY ALTERNATE CONTACT	POSITION	EMPLOYER	ALTERNATE CONTACT LOCATION	ALTERNATE TELEPHONE

REPORT LINE USE ONLY

N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					