



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee	Licensee Representative
Areva Resources Canada Inc.	Daniel Zunti, Stephanie Forseille
Licence No. / Expiry	Representative's Title
2BE-KIG1318/ July 21st, 2024	Exploration Representatives
Land / Other Authorizations	Land / Other Authorizations
IOL KVL3006C02	N2014C0014
Date of Inspection	Inspector
July 10 <sup>th</sup> 2017	WRO C. Wilson
Activities Inspected	
<input checked="" type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage	
<input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: <input type="checkbox"/> Other: <input type="checkbox"/> Other:	

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.__)	<input type="checkbox"/> Action Required (s.__)
<p>Summary</p> <p>On July 10<sup>th</sup>, 2017 Indigenous and Northern Affairs Canada’s Water Resource Officer, Christine WILSON completed a regularly scheduled compliance inspection of Areva Resources Canada’s Kiggavik Project (photo 1) - water licence no. 2BE-KIG1318. The following report was produced with the findings of that inspection.</p> <p>Observations</p> <ol style="list-style-type: none"><li>1. The project is in temporary closure/care and maintenance, with no staff at the Kiggavik Camp.</li><li>2. The infrastructure remains in place with the window and doors secured to protect from disturbances while vacant (photo 3). The structures appear to be in good condition.</li><li>3. Most hazardous materials have been removed. The remaining are secured or stored appropriately.</li><li>4. The water conveyance line from the unnamed water lake has been removed.</li><li>5. The waste water sump and lines are still in place but the inspector has no concerns (photo 4).</li><li>6. The controlled open burn location was inspected, no concerns from the water licence perspective; the cleanup of the site was done well. The inspector would like to see this activity 31 plus meters from the high water mark to avoid any run off from entering a water body.</li><li>7. The bulk fuel storage facility (photo 2) has a total of eight tanks, all which are empty. The distribution hook up remain with two small ply wood structures -which were secured- and some spill kits. No apparent spills noted any concerns.</li></ol>			
SECTION 2	<input type="checkbox"/> Comments (s.__)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s.__)
<p>No concerns at this time.</p>			
SECTION 3	<input type="checkbox"/> Comments (s.__)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s.__)	<input checked="" type="checkbox"/> Action Required (s.3)
<p>The inspector had no concerns with the state of the camp or any of the documents filed with the Nunavut Water Board. The proponent representatives are, as always, operating the project with best practice principals.</p> <p>Please be in contact with your new inspector Atuat Shouldice at 1-867-645-2840 or <a href="mailto:Atuat.Shouldice@aandc.gc.ca">Atuat.Shouldice@aandc.gc.ca</a> as plans for the project change.</p>			

Licensee or Representative	Inspector's Name
	C. Wilson
Signature	Signature
	Original signed on file
Date	Date
	August 1 <sup>st</sup> , 2017

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

cc. Erik Allain, Manager Field Operations, INAC  
Stephanie Forseille, SHEQ Coordinator, Areva Resources Canada Inc.

Attached: Photo Log 07.10.17





PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
July 11 <sup>th</sup> , 2017	2BE-KIG1318	Sony DSC-HX50V Cyber shot	WRO Wilson
Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)		
Photo 1	N64° 26' 26.00", W97° 39' 31.46"		



Description:  
Kiggavik Camp



Locations name:

Photo 2

Lat/Long (DD.MM.SS.SS, NAD83)

N64° 25' 33.54", W97° 43' 18.43"



Description

Bulk Fuel Farm- All the tanks are empty





Locations name:  
Photo 3

Lat/Long (DD.MM.SS.SS, NAD83)  
N64° 26' 26.00", W97° 39' 31.46"



Description  
Building are secure



Locations name:

Lat/Long (DD.MM.SS.SS, NAD83)

Photo 4

N64° 25' 33.54", W97° 43' 18.43"



Description

Bulk Fuel Farm- All the tanks are empty