



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 07-17-2014	REPORT TIME 10:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR		REPORT NUMBER -
B	OCCURRENCE DATE: MONTH – DAY – YEAR 07-16-2014	OCCURRENCE TIME 15:15	<input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) N2014C0001		WATER LICENCE NUMBER (IF APPLICABLE) 2BE-KIG1318		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION 3.9km SW of AREVA Kiggavik camp			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES 64 MINUTES 24 SECONDS 50.78		LONGITUDE DEGREES -97 MINUTES 42 SECONDS 23.67		
F	RESPONSIBLE PARTY OR VESSEL NAME AREVA Resources Canada Inc	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Box 9204 817 45th St. West Saskatoon, SK S7K 3X5			
G	ANY CONTRACTOR INVOLVED Boart Longyear	CONTRACTOR ADDRESS OR OFFICE LOCATION 4025-96 Avenue S.E. Calgary, AB T2C 4T7			
H	PRODUCT SPILLED Drill cuttings	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES Unknown		U.N. NUMBER N/A	
	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A		U.N. NUMBER N/A	
I	SPILL SOURCE Drill cuttings discharge site	SPILL CAUSE Drill discharge too close to water		AREA OF CONTAMINATION IN SQUARE METRES 20 square meters	
J	FACTORS AFFECTING SPILL OR RECOVERY N/A	DESCRIBE ANY ASSISTANCE REQUIRED N/A		HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT N/A	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS Drill cuttings discharge drained downhill into a small water body located about 50m away after discharge material became re-activated, possibly due to recent heavy rains in the area. White discoloration noted in the adjacent edge of the water body as the white, silty material composing the discharge flowed away from the original discharge site and into the water. The discharge site originated from a recent non-mineralized drill hole and contained a single day's worth of discharge material. Following discovery, the excess clean water and cuttings discharge hoses from a nearby drill were relocated further away to reduce risk of further re-activation and a berm was built surrounding the discharge site to prevent further seepage of cuttings material into the water body.				
L	REPORTED TO SPILL LINE BY Curtis Rhinas	POSITION SHEQ Supervisor	EMPLOYER AREVA	LOCATION CALLING FROM Kiggavik Camp	TELEPHONE 306-683-9562
M	ANY ALTERNATE CONTACT	POSITION	EMPLOYER	ALTERNATE CONTACT LOCATION	ALTERNATE TELEPHONE

REPORT LINE USE ONLY

N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					