



Indian and Northern  
Affairs Canada

Affaires indiennes  
et du Nord Canada

CIDM#516544

**Water Licence: 2BE-KIR0812 Triex Minerals Corp. (subsidiary of Canterra Minerals); Land Use Permit: 2005C0023**

**Inspection photographs –July 28, 2010 for Kirwan Lake camp at coordinates  
N67° 17' 53.1" W116° 52' 55.7" (NAD 83)  
(taken by Water Resource Officer M. Joy)**

**Photograph 1: Aerial view of dismantled Kirwan Lake camp site**







Indian and Northern  
Affairs Canada

Affaires indiennes  
et du Nord Canada

CIDM#516544

**Water Licence: 2BE-KIR0812 Triex Minerals Corp. (subsidiary of Canterra Minerals); Land Use Permit: 2005C0023**

**Photographs 2 & 3: Panels of plywood left unsecured on site**



**Photographs 4 & 5: Former sump locations were backfilled with large rocks but not restored adequately. Backfill materials are too large for proper contouring and compaction to prevent permafrost degradation.**







CIDM#516544

**Water Licence: 2BE-KIR0812 Triex Minerals Corp. (subsidiary of Canterra Minerals); Land Use Permit: 2005C0023**

**Photographs 6 & 7: Trench that was created to assist with sump drainage was not backfilled. Trench is fairly extensive with several areas that have been widened out.**



**Photograph 8: Former latrine site was not recontoured**



**Photograph 9: Pile of debris left near former float dock site**







CIDM#516544

**Water Licence: 2BE-KIR0812 Triex Minerals Corp. (subsidiary of Canterra Minerals); Land Use Permit: 2005C0023**

**Photograph 10: Site used for open burning –ash, metal and glass debris left behind**



**Photograph 11: Site used for open burning –metal and debris left behind**

