

License No: NWB2KIR0507

Issued Date: September 15, 2005

Expiry Date: October 28, 2012

Project Name: Mountain &amp; Dismal Lk, Dismal Lk W &amp; Kendall R Properties

Licensee: Triex Minerals Corporation

Mailing Address: P.O. Box 11584  
1410 - 650 West Georgia Street  
Vancouver, BC V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

As above

General Background Information on the Project (\*optional):

Early stage uranium exploration property

Licence Requirements: the licensee must provide the following information in accordance with

Part B

Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Domestic - unnamed lake adjacent to camp

Water Quantity:

5 m<sup>3</sup>

Quantity Allowable Domestic (cu.m)

~1.14 m<sup>3</sup>/day

Actual Quantity Used Domestic (cu.m)

15 m<sup>3</sup>

Quantity Allowable Drilling (cu.m)

~35.96m<sup>3</sup>/24hr  
shift

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☒ Sewage☒ Drill Waste☒ Greywater☐ Hazardous☐ Other:

Additional Details:

Nunavut Water  
Board

JUN 12 2009

Public Registry

Date of Spill:  (as reported to the Department)  
Date of Notification to an Inspector:   
Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

**Revisions to the Spill Contingency Plan**

SCP submitted and approved - no revision required or proposed



Additional Details:

**Revisions to the Abandonment and Restoration Plan**

AR plan submitted and approved - no revision required or proposed



Additional Details:

**Progressive Reclamation Work Undertaken**

Additional Details (i.e., work completed and future works proposed)

Natural depressions were used as drill sumps, no digging or backfilling required.  
All garbage and empty fuel drums have been removed from the property on an ongoing basis.  
Upon completion of exploration project, all structures, equipment and fuel drums will be removed, and all work sites will be restored as required.

**Results of the Monitoring Program Including:**

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details attached



Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details attached



Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Inspection Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

Date: Aug. 3, 2008

Inspector: Melissa Joy

Company Rep: Justin Rensby - Ridge Resources

Details:

Inspection took place as camp was being shut down. No water samples were taken. Main issues were no mercury spill kit for domestic UV water filter, no secondary containment for fuel in large cache areas (bermed only), saturated ground susceptible to erosion and scummy (grey water sump area for kitchen/dry), and need to submit hazardous waste manifest upon clean up.

Anna North discussed inspection report with Melissa Joy verbally in September. It was noted that the issues could not be addressed in the winter time, but would be addressed in the 2009 field season, by a full clean up by Discovery Mining Services or similar agency. Before and after photos will be taken and submitted.

**Any additional comments or information for the Board to consider**

Triex Minerals Corporation is not planning a 2009 exploration program on this property. Full reclamation and clean up of the camp and area will be completed, details of which will follow in the 2009 annual report required to the NWB.

**Date Submitted:**

March 9, 2009

**Submitted/Prepared by:**

Anna North

**Contact Information:**

**Tel:** (604) 687-6680

**Fax:** (604) 687-1448

**email:** [anorth@diamondex.net](mailto:anorth@diamondex.net)

Source Description	Location Description	Latitude			Longitude		
		Deg	Min	Sec	Deg	Min	Sec
Lake	Camp	67	17	48	-116	52	34
Lake	Dismal Lake	67	29	56.5929	-117	41	17.3145
Lake	Helmut Lake	67	19	21.9443	-116	54	52.8295
Lake	Jenny Lake	67	17	38.5369	-116	57	12.8506
Pond	KR08-001	67	7	17.6223	-116	33	2.04013
Pond	KR08-002	67	7	2.1359	-116	30	2.4037
Pond	KR08-003	67	7	39.1263	-116	28	45.777

#### GPS Locations of areas of waste disposal

Location Description (type)		Latitude			Longitude		
		Deg	Min	Sec	Deg	Min	Sec
Kitchen Sump	Camp	67	17	50	-116	52	41
KR08-001	Drill Hole	67	7	17.6232	-116	33	2.4012
KR08-002	Drill Hole	67	7	2.136	-116	30	2.4048
KR08-003	Drill Hole	67	7	39.126	-116	28	45.7788
ML08-024	Drill Hole	67	18	54.054	-116	55	15.5964
ML08-025	Drill Hole	67	19	42.492	-116	55	15.438
ML08-026	Drill Hole	67	20	11.5764	-116	55	57.2016
ML08-027	Drill Hole	67	17	31.7148	-116	56	43.1124
ML08-027b	Drill Hole	67	17	31.8768	-116	56	43.0296
ML08-028	Drill Hole	67	17	39.264	-116	56	29.976
ML08-029	Drill Hole	67	17	37.266	-116	56	41.8488
DL08-09	Drill Hole	67	30	3.5388	-117	42	9.1116
DL08-10	Drill Hole	67	30	0.0504	-117	43	8.022
DL08-11	Drill Hole	67	29	47.2416	-117	42	58.0248