



WATER USE INSPECTION REPORT

| | |
|--|---|
| Date: July 7, 2011 | Licensee Rep. (Name/Title): John Witteman |
| Licensee: Agnico Eagle Mines Ltd. (Agnico) | Licence No.: 2BE-MEP0813 |

At the time of the inspection the Meliadine East Project was being decommissioned. Agnico-Eagle (Agnico) had already begun the back haul of materials to the Meliadine West site. The camp was no longer occupied and no water was being used.

WATER SUPPLY

| | |
|--|--|
| Source(s): Atulik Lake | Quantity Permitted: 30 cubic meters (M3) |
| Owner:/Operator: Agnico Eagle Mines Ltd. | |

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | | |
|-----------------------|-----------------------|-----------------------|----------------------|
| Intake Facilities: NA | Storage Structure: NA | Treatment Systems: NA | Chemical Storage: NA |
| Flow Meas. Device: NA | Conveyance Lines: NA | Pumping Stations: NA | Screen : NA |

Comments: This camp is being decommissioned and no water is being used.

- Some PVC piping remains around site and will have to be removed.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Primary – Discharge to Sump

| | | |
|------------------------|--|------------|
| Natural Water Body: NA | Continuous Discharge (land or water): NA | |
| Seasonal Discharge: NA | Wetlands Treatment: NA | Trench: NA |

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | |
|----------------------------|-----------------------------|--------------|
| Discharge Quality: NA | Decant Structure: NA | Erosion: NA |
| Discharge Meas. Device: NA | Dyke Inspection: NA | Seepages: NA |
| Dams, Dykes: NA | Freeboard: NA | Spills: NA |
| Construction: NA | O&M Plan: NA | A&R Plan: |
| Discharge: NA | Effluent Discharge Rate: NA | |

Comments: No greywater or sewage was being produced or discharged at the time of the inspection.

- All greywater and sewage sumps must be treated and reclaimed.

Solid Waste:

Owner/Operator: Agnico Eagle Ltd.

| | | |
|--------------|---------------------|--------|
| Landfill: NA | Burn & Landfill: NA | Other: |
|--------------|---------------------|--------|

Comments:

- There are a number of drums of metals and various crates with metal wastes that will have to be shipped out for disposal.
- 6 wooden shacks and buildings will have to be torn down and disposed off properly.
- PVC piping and electrical wiring scattered around the site will have to be back hauled for proper disposal.
- There were a couple of garbage piles around the camp perimeter that should be cleaned up.
- A drillers shack, satellite tower and dish are still standing and will have to be removed for disposal.

FUEL STORAGE:

Waste Oil Storage: Hazardous Waste Transfer Area Owner/Operator: Agnico Eagle Ltd.

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | |
|------------------------|------------------------------------|-----------------------|
| Berms & Liners: NA | Water within Berms: NA | Evidence of Leaks: NA |
| Drainage Pipes: NA | Pump Station & Catchments Berm: NA | |
| Pipeline Condition: NA | Condition of Tanks: NA | |

Comments:

- All drums should be removed from site and disposed off accordingly.
- All propane cylinders should be back hauled for disposal.
- Any other chemicals and fuels/hydrocarbons must be removed for proper disposal.

SURVEILLANCE NETWORK PROGRAM (SNP)

| | | | |
|-----------------------------|------|------------------------------------|-----------------|
| Samples Collected | | Owner /Operator: Agnico Eagle Ltd. | |
| | | INAC:. None | |
| Signs Posted | SNP: | | Warning: Posted |
| Records & Reporting: | | | |
| Geotechnical Inspection: NI | | | |

Comments: No samples were taken during this inspection as the camp was not occupied and no exploration activities were occurring.

Non-Compliance of Act or Licence:

- Agnico is in the process of cleaning up this site. All terms and conditions in Part I of the current water licence (2BE-MEP0813) should be followed for the abandonment and restoration of this site.
- All materials removed from the site should be recorded and put into the annual report making sure to include the description and quantities of materials removed.
- After the abandonment and restoration of the site has been completed to the satisfaction of the Inspector, Agnico should provide future plans for the site, if any.

Ian Rumbolt

Sent by E-mail

Inspector’s Name

Inspector’s Signature