

NWB Annual Report Year being reported: 2018

License No: 2BE-MEP1828 Issued Date: November 1, 2018  
Expiry Date: October 31, 2028

Project Name: Meliadine East Project

Licensee: Agnico Eagle Mines Ltd.

Mailing Address: C.P. 87, 765 chemin de la mine Goldex  
Val-d'Or, Qc  
J9P 4N9

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with  
Part B Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Local lakes and ponds		
Water Quantity:	10m³/day	Quantity Allowable Domestic	
	0	Actual Quantity Used Domestic (cu.m)	
	289m³/day	Quantity Allowable Drilling	
	22m³/day (during 10 days)	Total Quantity Used Drilling	

- Waste Management and/or Disposal
- ☐ Solid Waste Disposal
  - ☐ Sewage
  - ☒ Drill Waste
  - ☐ Greywater
  - ☐ Hazardous
  - ☐ Other:

Additional Details:  
8 drill holes were done and drill waste (cutting) was disposed of in natural depressions located at a distance of at least thirty-one (31) metres from any water body and where direct flow into water body is not possible.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)  
Date of Spill:  
Date of Notification to an Inspector:  
Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)  
No unauthorized discharge in 2018.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed  
Additional Details:

Revisions to the Abandonment and Restoration Plan

Other: (see additional details)

Additional Details:

An update of the plan was submitted to the board in November 2018.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

The drilling casings were removed at the end of the drilling, or cut off at ground level if they could not be removed. A final inspection was made when the drilling was completed to ensure that no remaining waste or material was present.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

No artesian flow occurrence. Waste generated during the exploration was transported to the Meliadine site.

Date Submitted:	December 6, 2018
Submitted/Prepared by:	David Frenette
Contact Information:	Tel: 819.874.5980 ext. 3622
	Fax:
	email: <a href="mailto:david.frenette@agnicoeagle.com">david.frenette@agnicoeagle.com</a>



### GPS Coordinates for water sources utilized

Source Description	Latitude			Longitude		
	Deg °	Min '	Sec "	Deg °	Min '	Sec "
Pond	62	51	57	91	20	33
Pond	62	52	13	91	21	23
Pond	62	51	48	91	18	35

### GPS Locations of areas of waste disposal

Drilling waste (cutting) was disposed of proximal to drill holes and below are the drill holes coordinates.						
Location Description (type)	Latitude			Longitude		
	Deg	Min	Sec	Deg	Min	Sec
	°	'	"	°	'	"
M18-2478	62	51	55	91	20	40
M18-2479	62	51	57	91	20	42
M18-2481	62	52	0	91	20	44
M18-2487	62	52	1	91	20	47
M18-2489	62	52	5	91	20	59
M18-2492	62	52	11	91	21	12
M18-2493	62	52	4	91	20	53
M18-2494	62	51	56	91	18	31