

Attachment 5:
INAC Land Use Permit Inspection Report
(August, 2016)



☒ Original
☐ Follow-Up Report

LAND USE PERMIT INSPECTION FORM

Permittee	Representative
Sabina Gold & Silver Corp	John Laitin
Permit No. / Expiry	Representative's Title
N2012C0003	Manager – Site Operations
Other Authorizations	Land / Other Authorizations
Date of Inspection	Inspector
9 & 10 August 2016	Baba Pedersen
Activities Inspected	
<input type="checkbox"/> Camp <input checked="" type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage	
<input type="checkbox"/> Roads/hauling <input type="checkbox"/> :Other <input type="checkbox"/> Other:	

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable	
Section:				Term No.	Condition	Observation No.
31 (1)(a) Location and Area					A	
31 (1)(b) Time					A	
31 (1)(c) Equipment						
31 (1)(d) Methods and Techniques					A	2
31 (1)(e) Type location, capacity and operation of facility						
31 (1)(f) Control or prevent of flooding, erosion, and subsidence of Land						
31 (1)(g) Use, storage, handling and disposal of chemical or toxic materials					C	1
31 (1)(h) Wildlife and fisheries habitat						
31 (1)(i) Objects and places of recreation, scenic and ecological value						
31 (1)(k) Petroleum fuel storage					A	
31 (1)(m) Matters not inconsistent with the regulations						

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input type="checkbox"/> Action Required
I Inspected 2 locations associated with this Land Use Permit (LUP). 1 st was the Wishbone 1 Fuel Cache Site (Photo 1) @ N 65* 43’ 08.5” W 107* 58’ 53.3” on August 9 th , and 2 nd were 3 Randomly Selected Drill Holes very close to each other near the Goose Camp (Photos 2, 3, 4 & 5) on Aug 10 th .			
SECTION 2	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input type="checkbox"/> Action Required
1. I found 1 busted open bag of white powder at the Wishbone 1 Fuel Cache Site, all Fuel has been removed. 2. The Drill Holes were nicely cleaned up with only small Marker Sticks (Photo 3) left behind. The 3 rd Drill Site I checked (Photo 5) had a Wire going into it for what appeared to be a Monitoring Station.			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input checked="" type="checkbox"/> Action Required
1. The bag of white powder at the Wishbone 1 Fuel Cache site needs to be cleaned up and removed. 2. Once the Drill Sites are done being used the Marker Sticks and any Monitoring Stations must be removed.			
Licensee or Representative	Inspector's Name		
	Baba Pedersen		
Signature	Signature		
	Original Signature on File		
Date	Date		
	30 November 2016		

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

Cc Erik Allain, INAC Iqaluit, Manager Field Operations

Tracey McCaie, INAC Iqaluit, Manager Land Administration



Date	Camera	Inspector	Authorization
9 & 10 Aug 2016		Baba Pedersen	N2012C0003
Photo Log # 6634		Location N 65° 43' 08.5" W 107° 58' 53.3"	
Photo 1			
Description: Wishbone 1 Fuel Cache Site with 1 Bag of white powder			



Photo Log # 6852

Photo 2

Description: Map showing Drill Hole locations on Crown Land near Goose Camp




Photo Log # 6889

Location N 65° 31' 34.1" 106° 24' 45.1"

Photo 3

Description: Drill Hole 1 of 3 that I checked





Photo Log # 6896

Location N 65° 31' 34.5" W 106° 24' 39.0"

Photo 4

Description: Drill Hole 2 of 3 that I checked



Photo Log # 6905

Location N 65° 31' 35.3" W 106° 24' 33.2"

Photo 5

Description: Drill Hole 3 of 3 that I checked

