NWB Annual	Report	Year being reported: Select ▼				
License No:	2BE-MLL1722	Issued Date: June 30, 2017 Expiry Date: June 29, 2022				
	Project Name:	Vishbone-Malley Project				
	Licensee: SABIN	A GOLD AND SILVER CORP				
	Mailing Address:	#1800 - 555 Burrard Street, Box 220, Vancouver, BC, V7X 1M7				
	Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):					
	SABINA GOLD AND	SILVER CORP				
General Background Information on the Project (*optional):						
	Located approximate	ely 50 km west of Sabina's Back River Project.				
Licence Requirements		eee must provide the following information in accodance				
A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.						
nuoto munus	Water Source(s): Water Quantity:	N/A  70 Quantity Allowable Domestic (cu.m)  Actual Quantity Used Domestic (cu.m)  130 Quantity Allowable Drilling (cu.m)  Total Quantity Used Drilling (cu.m)				
	Waste Management a Solid Waste Disp Sewage Drill Waste Greywater Hazardous Other: Additional Details:	osal				
	occured.	as not operational in 2018. No water use or waste disposal				

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: (as reported to the Spill Hot-line)					
	Date of Spill: Date of Notification to an Inspector:					
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)					
	N/A					
Davisiana ta	ha Cuill Continues and Dian					
Revisions to	he Spill Contingency Plan  SCP submitted and approved - no revision required or proposed					
[	Additional Details:					
	Submitted June 2018					
l						
Revisions to	he Abandonment and Restoration Plan					
	AR plan submitted and approved - no revision required or proposed					
	Additional Details:					
	Submitted March 2017					
Progressive	eclamation Work Undertaken					
. regioeenie	Additional Details (i.e., work completed and future works proposed)					
	Progressive reclamation were not undertaken.					
Docults of th	Monitoring Program including:					
Results of th	Monitoring Program including.					
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) o					
	each location where sources of water are utilized;  Not Applicable (N/A)					
	Additional Details:					
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude each location where wastes associated with the licence are deposited;	) of				
	Not Applicable (N/A)					
	Additional Details:					
	Additional Details.					

## Results of any additional sampling and/or analysis that was requested by an Inspector

	No additional sampling requested by an Inspector or the Board	•			
r	Additional Details: (date of request, analysis of results, data attached, etc)	_			
Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.					
	No additional sampling requested by an Inspector or the Board	7			
	Additional Details: (Attached or provided below)				
Any respons	ses or follow-up actions on inspection/compliance reports				
	No inspection and/or compliance report issued by INAC	7			
,	Additional Details: (Dates of Report, Follow-up by the Licensee)				
Any additional comments or information for the Board to consider					
L					
Date Submitt					
Submitted/Pr Contact Infor					
Jonatinio	Fax:				
	email: <a href="mailto:mkeefe@sabinagoldsilver.com">mkeefe@sabinagoldsilver.com</a>				