

BACK RIVER PROJECT

2021 Annual Report for Water Licence 2BE-MLL1722

Prepared by RainCoast Environmental

Prepared for Sabina Gold and Silver Corp.

Submitted to Nunavut Water Board

June 2022

BACK RIVER PROJECT

2021 2BE-MLL1722 Annual Report

Table of Contents

Table	of Con	tents		
Acrony	yms		i	
Execu	tive Su	mmary - English	1 -1	
ΔοΔο	ティ┍८८	ξ ^{τь} - ΔΔ ⁶ ΠϽ ^ι Ρ≪ ² Ϲ ⁻ Γ ^ι	1-2	
Ataniu	ıyunut	Nainaqhimayuq - Inuinnaqtun	1-3	
1.	Intro	ductionduction	1-4	
2.	Annual Report per Part B, Item 2			
	a.	Summary of Water Use and Waste Disposal		
	b.	Quantity of Water Use from Inuit Owned Lands		
	c.	Quantity of Water Use from Crown Lands		
	d.	Quantity of Waste Disposed On-Site	2-5	
	e.	Quantity of Waste Backhauled		
	f.	Unauthorized Discharges and Follow-up	2-5	
	g.	Management Plan Revisions	2-5	
	h.	Progressive and Final Reclamation	2-5	
	i.	Artesian Flows	2-5	
	j.	Information Requests and Results of Monitoring Program	2-5	
	k.	Sumps and Drill Hole Locations	2-5	
	ι.	Temporary Camp Location(s)	2-6	
	m.	Summary of Contruction Activity/Modifications	2-6	
	n.	Consultation Summary	2-6	
	ο.	Board Requests Re: Water Use and Waste Disposal	2-6	
Annen	dix A N	NWB Annual Report Form	2-1	

BACK RIVER PROJECT i

Acronyms

CIRNAC Crown Indigenous Relations and Northern Affairs Canada

KIA Kitikmeot Inuit Association
The Licence Water Licence 2BE-MLL1722
NIRB Nunavut Impact Review Board

MLA Marine Laydown Area

NWB Nunavut Water Board

The Project Back River Project

Sabina Gold & Silver Corp.

ii JUNE 2022

Executive Summary - English

Sabina Gold & Silver Corp. (Sabina) has filed its Annual Report on its activities during 2021 under Water Licence No. 2BE-MLL1722 (the Licence) issued by the Nunavut Water Board. As set out in Part B, Item 2 of the Licence, the report includes information with respect to the following topics:

- A summary report of water use and waste disposal;
- A list of unauthorized discharges and a summary of follow-up actions taken;
- Any revisions to plans under this Licence;
- A description of all progressive and or final reclamation work undertaken, if any, including photographic records of site conditions before, during and after completion of operations;
- A report of any artesian flow occurrences;
- Any temporary camp locations;
- Any other details on water use or waste disposal requested by the Board.

BACK RIVER PROJECT 1-1

$\Delta \sigma \Delta \dot{\sigma}_{e} L L_{e} - \Delta \sigma_{e} U C L_{e}$

- $\Delta\Delta\dot{\alpha}^{5}$ /L γ^{5} $\Delta\sigma\dot{b}^{5}$ Δ L γ^{5} Δ^{5} σ^{5} J γ^{5} Δ^{5} L γ^{5} Δ^{5} C $\dot{\alpha}$ σ^{5} J γ^{5}
- $\mathsf{UV}_{\mathsf{P}} = \mathsf{UV}_{\mathsf{P}} = \mathsf{$
- ▷¹Ы▷৴¹Ы™ጋ™ СLՃዮታ೨₾Ċ™ ለペ゚ႠჃჾႦჄჾჁ ላჼႱ೨ ▷ペጲ೨°Ⴃ゚ ዮႮႠႪჇჼჃ
 ▷Ი™በበሲσ▷ጚ, ለር¹Ы™<', Δϲ▷<೨ቦ ላፆትႠ▷™С▷ጕ៤ጚ <<С▷ጚ Δσ▷ጚ・
 ¹Խ൧Ճ°ԾჀ൧゚ ґഊႣჃႮ, ◁▷ċ™በՙበσ▷በ゚೨Ⴎ ላჼႱ೨ ዮႮႫჃႮ ለዻሙበ゚೨ቦ゚ ላ▷ċ™በՙበԾ゚:
- >σ<bs \(\delta \sigma \sig
- ΛC'b%<' Δα-
 Δαθρίως
- ተወጋል° ወልና ላተጐቦና ወጋ ወልታም ተLተና ልLናቦ ላጋናውና Jና ኦ የ ላታሮ ታ የ ላኮር ታ የ ላ

1-2 JUNE 2022

Ataniuyunut Nainaqhimayuq - Inuinnaqtun

Sabina Gold & Silver Corp. (Sabina) tuniyat Ukiumun Tuhaqhitaut huliniqmingnut atuqtitlugu 2021 malikhugu Imaqmun Laisa Nappaa 2BE-MLL1722 (tamna Laisa) tuniyat tapkuat Nunavut Imaliriyit Katimayit. Ihuaqhaqniagut talvani Ilanga B, Tiraq 2 talvani Laisa, tamna tuhaqhittaut ilalik tuhagakhat piplugu tahapkuat pityutit:

- Tamna nainaghimayug tuhaghitaut immag atugnia igakutlu igagni;
- Titiqat pilaqtitnagit kuvipkaqni naunainaqnialu kinguagurutit huliniit piyauni;
- Kitutliqak nutanguqtauni parnautit malikhugu una Laisa;
- Unniqtut tamaitnut pivaliayauni tamnalu uvaluniit kingulliqpaq halumaqtirini havat havariyauni, piqaqat, ilautitlugit piksaliuqhimayut titiqnit havakviup qanuritni hivuani, atuqniani kinguagutlu iniqtauni aulatyutit;
- Tuhaqhitaut kitunutliqak immaktaqvit nunap iluanit piyaunit;
- Kitutliqak atullaktut hiniktaqvit inait;
- Kitutligak ahii unniqtuttiaqni immap atugni uvaluniit igakut igagni tukhiatai Katimayit.

BACK RIVER PROJECT 1-3

1. Introduction

This report to the Nunavut Water Board (NWB) has been prepared to summarize the project activities and monitoring undertaken by Sabina Gold and Silver Corp. (Sabina) during 2021, in accordance with Part B, Item 2 of License 2BE-MLL1722 (the Licence). The NWB Annual Report Form can be found in Appendix A of this report.

Wishbone-Malley Project is part of Sabina's overall Back River Project which includes the George and Goose exploration camps, the mine facilities under construction at Goose, the Marine Laydown Area (MLA) at Bathurst Inlet, and interconnecting ice and winter roads.

There is currently no infrastructure or equipment located at the Wishbone-Malley exploration area, although the Licence permits the construction of seasonal or temporary camps. Sabina continues to support Wishbone-Malley exploration activities out of existing Back River Project facilities, minimizing cumulative exploration activity footprint. This includes the housing of personnel at Goose, George or Marine Laydown Area (MLA) camps and making use of approved facilities and management plans for those sites, including in for the disposal of wastes.

No infrastructure or equipment is currently located at the Wishbone-Malley Project and no exploration activities took place in 2021.

1-4 JUNE 2022

2. Annual Report per Part B, Item 2

This section of the report has been constructed to address each of the requirements of Part B, Item 2 of the Licence. For ease of comparison, each subheading corresponds directly with the identically alphabetized subheading of Part B, Item 2 of Water Licence 2BE-GEO2025.

A. SUMMARY OF WATER USE AND WASTE DISPOSAL

No water was used under this Licence or wastes deposited in 2021.

B. QUANTITY OF WATER USE FROM INUIT OWNED LANDS

No water was withdrawn under this Licence from water sources located on Inuit Owned Lands in 2021.

C. QUANTITY OF WATER USE FROM CROWN LANDS

No water was withdrawn under this Licence from water sources located on Crown Land in 2021.

D. QUANTITY OF WASTE DISPOSED ON-SITE

No waste was generated or disposed of under this Licence in 2021.

E. QUANTITY OF WASTE BACKHAULED

No waste was generated or backhauled under this Licence in 2021.

F. UNAUTHORIZED DISCHARGES AND FOLLOW-UP

No hydrocarbon spills to water or triggering the NWT/NU spill reporting thresholds occurred in 2021.

G. MANAGEMENT PLAN REVISIONS

Sabina did not make any revisions to any management plans applicable to this Licence in 2021.

H. PROGRESSIVE AND FINAL RECLAMATION

No reclamation activities related to this Licence were undertaken in 2021. No structures or equipment have been constructed.

I. ARTESIAN FLOWS

No drilling took place under this licence in 2021 and no artesian flows were intercepted.

J. INFORMATION REQUESTS AND RESULTS OF MONITORING PROGRAM

No water was used for any purposes under this Licence in 2021. No water was discharged in 2021.

No inspections were conducted by CIRNAC specific to this Licence in 2021.

K. SUMPS AND DRILL HOLE LOCATIONS

No drilling or discharge to sumps took place in 2021.

BACK RIVER PROJECT 2-5

L. TEMPORARY CAMP LOCATION(S)

No temporary camps were established under this Licence in 2021.

M. SUMMARY OF CONTRUCTION ACTIVITY/MODIFICATIONS

No construction activity, modifications or major maintenance took place in 2021.

N. CONSULTATION SUMMARY

No consultation specific to this Licence was undertaken in 2021.

O. BOARD REQUESTS RE: WATER USE AND WASTE DISPOSAL

No requests related to water use or waste disposal were made by the Board in 2021.

2-6 JUNE 2022

Appendix A NWB Annual Report Form

BACK RIVER PROJECT 2-1

NWB Annual	Report	Year being reported: Select ▼ 2021								
License No:	2BE-MLL1722	Issued Date: June 30, 2017 Expiry Date: June 29, 2022								
	Project Name:	WISHBONE-MALLEY PROJECT]							
	Licensee: SABINA GOLD AND SILVER CORP									
	Mailing Address:	#1800 - 555 Burrard Street, Box 220, Vancouver, BC, V7X 1M7								
	Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):									
	SABINA GOLD AND SILVER CORP									
General Bac	General Background Information on the Project (*optional):									
Licence Req	uirements: the lice	ensee must provide the following information in accodance with								
	iter; sewage and g	e and waste disposal activities, including, but not limited to: method greywater management; drill waste management; solid and hazardo								
waste mana	Water Source(s): Water Quantity:	N/A 70 Quantity Allowable Domestic (cu.m/day) 0 Actual Quantity Used Domestic (cu.m/yr) 130 Quantity Allowable Drilling (cu.m/day) 0 Total Quantity Used Drilling (cu.m/yr)								
	Waste Manageme Solid Waste D Sewage Drill Waste Greywater Hazardous Other: Additional Details: No activities were									
A list of unau		ges and a summary of follow-up actions taken.								
	Spill No.: 0 Date of Spill: N/A	(as reported to the Spill Hot-line)								

	Date of Notification to an Inspector: Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)	
Revisio	ns to the Spill Contingency Plan	
	Other: (see additional details)	
	Additional Details:	
	See Section 2.G. of Annual Report. Sabina is updating the SCP and will submit the revised plan with the renewal application for this Licence.	
Revisio	ns to the Abandonment and Restoration Plan	
	Other: (see additional details)	
	Additional Details: See Section 2.G. of Annual Report. Sabina is updating the A&R and will submit the revised plan with the renewal application for this Licence.	
Progres	sive Reclamation Work Undertaken	
J	Additional Details (i.e., work completed and future works proposed)	
	See Section 2.H. of Annual Report.	
Results	of the Monitoring Program including:	
roound	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of eac	h
	location where sources of water are utilized;	
	Not Applicable (N/A)	
	Additional Details:	
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of eac location where wastes associated with the licence are deposited;	h
	Not Applicable (N/A)	
	Additional Details:	
	Additional Details: Results of any additional sampling and/or analysis that was requested by an Inspector	

	. 3					
	Additional Details: (d	date of request, a	nalysis of results,	data attached, etc)		
Any other de reported.	etails on water use o	or waste disposa	al requested by the	he Board by Novembe	r 1 of the y	ear being
	No additional sampling i	equested by an Inspe	ector or the Board		•	
	Additional Details: (A	Attached or provid	ded below)			
A			/lion	an auto		
Any respons	es or follow-up acti			eports		
	Inspection Report receive	ed by the Licensee (Da	ate):			
	Additional Details: (I	Dates of Report, I	Follow-up by the L	icensee)		
Any additional comments or information for the Board to consider						
,						
Date Submit Submitted/P Contact Info	repared by: Merle rmation: Tel:	13, 2022 Keefe/Katsky Ve	nter			
	Fax: email	mkeefe@sabin	agoldsilver.com			