



Photos of July 13 2014 Inspection 2BE-MOU1419



Figure 1. Drill setup at site (B). Note litter strewn around the site from bear damage.



Figure 2. Damaged emergency shelter, salt bags.





Figure 3. Dissolved salt and resulting dead vegetation. This impact will spread over time until salt is removed.



Figure 4. Timbers noted 5 km north of drill setup.





Figure 5. Litter accumulating in kitchen sump.



Figure 6. Fuel Cache (A) - barrels at base of hill.





Figure 7. Fuel Cache (A) - barrels and wood on top of hill.



Figure 8. Pallets, core boxes, and propane tanks stored on lake bank.





Figure 9. Camp aerial view - 3 berms shown in lower left corner.



Figure 10. Berm covers are damaged. Cap was left off and (potentially contaminated) water drained out.





Figure 11. Tall heating fuel setup. No secondary containment for the tank and valves.