

**WATER LICENCE INSPECTION FORM**☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Anconia Resources Corporation	Jason Brewster
Licence No. / Expiry	Purpose
2BE-MRC1217/ April 15 th , 2017	Exploration
Land Authorization No. / Expiry	Project Name
N2012C0006/ February 27 th , 2019	Marce Project
Date of Inspection	Inspector
September 16 th , 2021	RMO C. Wilson
Activities Inspected	
<input type="checkbox"/> Camp	<input checked="" type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:
<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage

SECTION 1	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
------------------	---	--	---

An inspection of Anconia Resources Corporation's ('Anconia'), Marce Project was completed by Crown-Indigenous Relations and Northern Affairs Canada's, Resource Management Officer, Christine Wilson ('Inspector'). The inspection was conducted to ensure compliance with applicable terms and conditions of water licence no. 2BE-MRC1217.

The following report was produced with observations noted by the Inspector at the Zak laydown located generally N62° 40' 15.73", W95° 28' 35.33" and information provided by Anconia on October 28th (appendix 1).

PRELIMINARY INFORMATION

- The Marce Project has been in a state of demobilization since 2016. Only materials stored at the Zak laydown authorized under the crown land use permit no. N2012C0006 remains to be clean-up.
- The 2019 clean-up was not completed as anticipated, and for that reason Anconia was granted a short term storage authorization under the Territorial Lands Use Regulations by Crown Indigenous Relations and Northern Affairs.
- In 2020-2021 the clean-up of the Zak laydown was finalized by a contractor on behalf of Anconia.

OBSERVATIONS

1. The materials located at the laydown have been removed; all the clean wood burned and ash backhauled (photo 1 and photo 2).
2. Numerous locations of windblown garbage is noted around the laydown (photo 3- photo 7). Materials as follows; three tarps, an oil jug, metal siding, a small secondary containment berm and insulation.
3. Three empty red and yellow drums (photo 8) are at the end of the airstrip at N62° 40' 9.5", W95° 29' 5.6".
4. Two drill holes at the West end of the air strip require removal or to be cut off at ground level. Locations are listed as follows:
 - drill site 1 approximately located at N62° 40' 6.04", W95° 29' 6.17" (photo 9); and
 - drill site 2 approximately located at N62° 40' 8.40", W95° 29' 7.01" (photo 10).

SECTION 2	<input type="checkbox"/> Comments (s. __)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s. __)
------------------	--	---	---

Non-compliance related to the terms and conditions of water licence 2BE-MRC1217:

PART I item 2: Failure to complete restoration work prior to the expiry of this Licence.

PART I item 4: Failure to remove materials from the land prior to the expiry of this Licence.

PART I item 8: Failure to reclaim drill holes to the satisfaction of the Inspector.

SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s.3)
------------------	--	---	--

Actions completed following the September 16th inspection:

- On September 17th, the Inspector communicated the observation noted in this report to the Permittee's contractor. The Permittee contacted the Inspector and committed to returning to the Zak laydown to complete the work prior to the end of the 2021 field season.
- On October 24th, the Permittee's contractor returned to the Zak laydown and completed an extensive clean-up.



- On October 28th pictures of all the materials removed (appendix 2) including the locations of five reclaimed drill sites were provided to the Inspector by the Permittee's contractor.

Upon review of the information provided by the Permittee's contractor, the Inspector has determined this will be a final inspection of the Marce (Zak laydown) project by Field Operations.

Licensee or Representative	Inspector's Name
	C. Wilson
Signature	Signature
	<i>Christie Wilson</i>
Date	Date
	November 9 th , 2021

Office Use Only: Follow-up report to be issued by Inspector

☐ Yes ☒ No



PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector:
September 16 th , 2021	2BE-MRC1217	Sony DSC-HX50V Cyber shot	WRO Wilson
Photo No.:		Lat/Long (DD.MM.SS.SS, NAD83):	
Photo 1		N62° 40' 15.73", W95° 28' 35.33"	



Description:
Zak Laydown



Photo No.:

Photo 2

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 20.1", W95° 28' 30.53"



Description:

Zak Laydown and adjacent esker airstrip.



Photo No.:

Photo 3

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 10.76", W95° 28' 33.40"



Description:

Metal siding and wood.



Photo No.:

Photo 4

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 8.23", W95° 28' 32.35"



Description:

Secondary containment berm.



Photo No.:

Photo 5

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 10.77", W95° 28' 27.07"



Description:

Oil Jug.



Photo No.:

Photo 6

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 7.52", W95° 28' 26.99"



Description:

Grey Tarp.



Photo No.:

Photo 7

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 9.05", W95° 28' 27.43"



16 09 2021

Description:

Green Tarp and insulation.



Photo No.:

Photo 8

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 9.50", W95° 29' 5.699"



Description:

Three empty red and yellow drums.



Photo No.:

Photo 9

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 6.04", W95° 29' 6.173"



Description:

Drill Site 1



Photo No.:

Photo 10

Lat/Long (DD.MM.SS.SS, NAD83):

N62° 40' 8.40", W95° 29' 7.01"



Description:

Drill Site 2



Anconia



Anconia



Anconia



Anconia



Anconia



Anconia





Anconia



Anconia



Anconia



Anconia



Anconia



Anconia



Anconia





Anconia







