



Photos of August 16th 2014 Inspection – 2BE-MSX0712



Figure 1. Waste noted on back of hill upslope from historic camp location (a).



Figure 2. Drill location c). Smaller debris was noted at other drill sites.



Figure 3. Cargo straps on bare patch to the north of location c).



Figure 4. Barrel noted downslope from drill location c).



Figure 5. Partially burned debris left at location e).



Figure 6. More debris at location e).



Figure 7. Core racks poised on the side of the hill, close to the camp location a).



Figure 8. Steep slope from the core racks to the lake. Racks are also within 30m of the water.



Figure 9. Fuel cache at location b). Dark spot is a hydrocarbon stain.



Figure 10. Closer view of hydrocarbon stain at b). Strong hydrocarbon smell remains in the humic (organic) layer.