

WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Terrane Metals Corp (Thompson Creek Metals Company)	Dave Bailey
Licence No. / Expiry	Representative's Title
2BE-MZE0712	Sr. Director of Environment
Land / Other Authorizations	Land / Other Authorizations
KIV308C03	IOL
Date of Inspection	Inspector
06/07/2015	WRO WILSON
Activities Inspected	
<div><input checked="" type="checkbox"/> Camp<input type="checkbox"/> Drilling<input type="checkbox"/> Mining<input type="checkbox"/> Construction<input checked="" type="checkbox"/> Reclamation<input type="checkbox"/> Fuel Storage</div> <div><input type="checkbox"/> Roads/Hauling<input type="checkbox"/> Other: Water Discharge<input type="checkbox"/> Other:</div>	

Conditions: **A - Acceptable** **C - Concern** **U - Unacceptable** **NA – Not Applicable** **NI – Not Inspected**

Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	NA		Water Management Structures	NA		Storage	NA	
Flow Measure. Device	NA		Culverts / Bridges	NA		Spills	A	3
Source:	NA		Drainage	NA		Spill Plan	NA	
Water Use:	NA		Erosion / Sediment	NA				
Recirculation (y /n)	NA		Mitigation Measures	NA		Administrative		
			Reclamation Activities	A	1,3	Records	NA	
			Materials Storage	NA		Reports	A	2
Waste Disposal			Signage	NA		Plans	A	1
Waste Water	NA					Notifications	A	1
Solid Waste	NA		Monitoring			Other		
Hazardous Waste	NA		Sample Collection / Analysis	NA				

**The number in the comments field will correspond with specific comments provided below.*

Samples taken by Inspector:	Location(s):
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

SECTION 1 ☒ Comments (s.1) ☐ Non-Compliance with Act or Licence (s.__) ☐ Action Required (s.__)

Pre inspection

1. 2BE-MZE0712 was issued to Terrane Metals Corp. (Terrane) on July 12th, 2007. Terrane was later acquired by Thomas Creek Metals Company who submitted a remedial action plan to the inspector in 2013 which detailed a commitment to restore the site to its original state.

2. The 2007 to 2012 annual reports have been submitted to the Nunavut Water Board and are available on the FTP site.

Observation

3. The following was noted;

-The camp, drums, and associated materials have been completely removed (see photo 2).

-A small area of burnt ground is located at N62 15’ 48.07”, W 93 37’ 38.06” though all ash appears to be removed (see photo 1).

-The area of noted contamination in the 2012 inspection report was removed 62 15’ 50.83” W 93 37’ 38.34”

SECTION 2 ☐ Comments (s.__) ☒ Non-Compliance with Act or Licence (s.2) ☐ Action Required (s.__)

No non-compliance with the Act or the 2BE-MZE0712 Licence.

SECTION 3 ☐ Comments (s.__) ☐ Non-Compliance with Act or Licence, (s.__) ☒ Action Required (s.3)

The Maze Lake Property has been restored to a natural state. This Inspector supports the closure or cancellation of this Licence.

Licensee or Representative	Inspector's Name
	WRO Wilson
Signature	Signature
	Original Signed on File
Date	Date
	July 6 th , 2015

Office Use Only: Follow-up report to be issued by Inspector ☐ Yes ☒ No



Date	Camera	Inspector	Licence
July 6 th , 2015	Sony Cyber Shot DSC-HX50V	WRO Wilson	2BE-MZE0712
Photo Log #	Location (NAD 83 DD MM SS.SS)		
Photo 1	N62° 15' 48.07", W 93° 37' 38.06"		
			
Description			
Area of burnt ground			

Photo Log #	Location (NAD 83 DD MM SS.SS)
Photo 2	N 62° 15' 48.53" W 93° 37' 33.73"
	
Description	
Maze Lake Property remediated	