

WATER LICENCE INSPECTION FORM

\times	Original		
	Follow-Up	Re	port

Licensee				Licensee Representative					
Strongbow Exploration Inc. N				N/A					
Licence No. / Expiry			Representa	tive's Title					
2BE-NTI0507 -									
Land / Other Authorizations			Land / Othe	er Authoriz	ations				
IOL: CO-20									
Date of Inspection			Inspector						
12/07/2014			Eva Pa	ul					
Activities Inspected	7					□			
		☐ Mining ☐ Construction ☐ Other:		Reclamation	☐ Fuel Storage	9			
	<u></u>								
	ceptable		- Unaccept	table	NA –	Not Applicable	NI – Not Ins	pected	
Water Use	Condition Comment	Site Conditions		Condition	Comment	Haz/Mat Manage	ement Condition	Comment	
Intake/Screen	NA	Water Management S	tructures	NA		Storage	NA		
Flow Measure. Device	NA	Culverts / Bridges		NA		Spills	NA		
Source:	NA	Drainage		NA		Spill Plan	NA		
Water Use:	NA	Erosion / Sediment NA		NA					
Recirculation (y /n)	NA	Mitigation Measure	s	NA		Administrative			
		Reclamation Activit	ies	U	1	Records	А		
		Materials Storage		NA		Reports	Α		
Waste Disposal		Signage		NA		Plans	NI		
Waste Water	Α					Notifications	NA		
Solid Waste	Α	Monitoring				Other			
Hazardous Waste	Α	Sample Collection /	Analysis	NA					
*Th	ne number in the o	comments field will co	rrespond v	vith speci	ific comr	nents provided belo	w.		
Samples taken by Inspec	ctor:	Location(s):							
☐ Yes ☐ No									
SECTION 1	Comments (s.1)	Non-Com	pliance w	ith Act o	r Licence	(s.2) X Act	tion Required (s	:.3)	
			•						
An inspection for the purposes of licence cancellation was conducted on July 12, 2014. Several sites were visited; camp and drill locations provided at the request of the Inspector. Drill activity is understood to have been conducted by Cominco at an earlier									
time. Coordinates are reported in NAD 83.									
 Findings are as follows: A. Drill (Hood-DDH-1) - N66°31′17.0″ W110°39′18.0″ – casing left uncut 									
B. Drill (Hood-DDH-6)- N66°31′21.0″ W110°40′12.0″ – casing left uncut									
C. Drill (Hood-DDH-7) - N66°31′14.9″ W110°40′15.6″ – casing left uncut									
D. Camp - N66°31'01.2" W110°40'37.2" – debris noted all around the lake									
E. Licence location - N66°50′00.0" W110°57′00.0" – nothing but core boxes just north of the licence location									
F. Camp - N66°33'07.9" W112°24'21.6" – nothing found									
G. Camp - N66°33'11.9" W112°22'48.0" – nothing found									
SECTION 2 Comments Non-Compliance with Act or Licence Action Required									
Part I Item 9: Failure to return areas to a pre-disturbed state upon completion.									
Part i item 9. Failure to return areas to a pre-disturbed state upon completion.									



Affaires autochtones et Développement du Nord Canada

SECTION 3	Comments	Non-Compliance with Act or Licence Action Required					
1. All debris left at the lake/camp location is to be removed.							
2. Drill casings for nearby drill sites are to be cut to the ground and capped (if feasible), however, it is understood that the drill							
collars pre-	collars pre-existed Strongbow's tenure on this property.						
Cancellation of	Cancellation of this licence is not recommended until location D (the 2005 fly camp) is restored to a re-disturbed state.						
Licensee or Repres	sentative		Inspector's Name				
-			Eva Paul				
Signature			Signature				
_			Sent electronically				
Date			Date				
-			28/11/2014				
APPENDICES:	Inspection Photos	Sample Resu	lts Other:				
Office Use Only:	Follow-up report to be issued by Inspecto	r	☐ Yes ☐ N	lo			
CC:	Phyllis Beaulieu, Manager of Licens	ing, NWB					

CC: Phyllis Beaulieu, Manager of Licensing, NWB
Erik Allain, Manager of Field Operations, AANDC



Photos of July 12, 2014 Inspection



Figure 1. Debris at the lake indicated as a camp location (coordinate 'D' above).



Figure 2. Further debris noted at the lake indicated as a camp location (coordinate 'D' above)

