



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Meliadine Gold Corp.	Glen Dickson
Licence No. / Expiry	Representative's Title
2BE-PET1114	President
Land Authorization No. / Purpose / Expiry	Land Authorization Expiry
IOL	---
Date of Inspection	Inspector
July 29 th , 2016	WRO Wilson
Activities Inspected	
<input type="checkbox"/> Camp <input checked="" type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input checked="" type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage	
<input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Water Discharge <input type="checkbox"/> Other:	

SECTION 1	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
<p>On July 29th, 2016 a regularly scheduled compliance inspection was conducted on Meliadine Gold Corp. (formally Canada Nickel Limited), Peter Lake Project. The inspection was conducted my Indigenous And Northern Affairs Canada’s Water Resource Officer Christine Wilson.</p> <p>This report was produced with the findings of that inspection and subsequent correspondence with the proponent.</p> <p><i>Observations</i></p> <ol style="list-style-type: none">1. A fuel cache remains at N63° 6’ 44.50”, W92° 31’ 12.19”. The cache has approximately 86 drums ranging from full, to partially full, and empty.2. The fuel is within a secondary containment berm (“berm”) but the structure was compromised with water.3. The water appears to be contaminated inside the berm.4. There appears to be some hydrocarbon staining on the ground where the berm may have over topped with water.5. The fuel drums are in poor condition, most labels appear to be incorrect or missing; all of the drums are rusting from being stored improperly. The drums appear to be repacked.6. An open burning pit was located at N63° 6’ 44.59”, W92° 31’ 13.6”. The pit had some remaining waste that should be removed but no impacts related to water noted.7. A few stacks of wooden timbers and core boxes also remain at the project. The materials were not tidy but no impacts related to water noted.8. No concerns noted with the drill sites. The cuttings were collected in a low area; the sites appear to be reclaimed to the satisfaction of the inspector.			
SECTION 2	<input type="checkbox"/> Comments (s. __)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s. __)
<p>Follow up is required.</p>			
SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s.3)
<p>The proponent will need to complete reclamation of this site before a final inspection can be issued by this office. The proponent will contact the Manager of Licensing, Nunavut Water Board, upon receipt of this report to ensure all obligations are met of this licence.</p>			

Licensee or Representative	Inspector's Name
	C. Wilson
Signature	Signature
	Sent by e-mail
Date	Date
	August 1 st , 2016

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

Attached: 2BE-PET1114, Photo Log- July 29nd, 2016
cc. Erik Allain, Manager Field Operations, AANDC
Manager of Licensing, NWB
Glen Dickson, Meliadine Gold Corp.



PHOTO LOG

Date: July 29 th , 2016	Authorization Number: 2BE-PET1114	Camera/Model: Sony DSC-HX50V Cyber shot	Inspector WRO Wilson
Photo No. Photo 1	Lat/Long (DD.MM.SS.SS, NAD83) N/A		



Description:
Peter Lake Project, Laydown area

Photo No. Photo 2	Lat/Long (DD.MM.SS.SS, NAD83) N63° 6' 43.12" W 92° 31' 10.99"
----------------------	--



Description:
Peter Lake Fuel Cache

Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)
-----------	-------------------------------



Photo 3

N63° 6' 44.50" W 92° 31' 12.20"



Description:

Secondary containment berm, hydrocarbon staining, contaminated water, rusted drums, poor condition of drums

Photo No.

Photo 4

Lat/Long (DD.MM.SS.SS, NAD83)

N63° 6' 44.79" W 92° 31' 13.65"



Description:

Open burning pit, some remiaing metal waste



Description: