

**WATER LICENCE INSPECTION FORM**☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Cameco Corporation	Kevin Parker
Licence No. / Expiry	Representative's Title
2BE-QAM1217/ May 31 st , 2017	Superintendent, Exploration Services
Land Authorization No. / Expiry	Project Name
Aberdeen Camp is on IOL	Turqavik- Aberdeen Project
Date of Inspection	Inspector
August 11 th , 2020	RMO C. Wilson
Activities Inspected	
<input checked="" type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Airstrip <input type="checkbox"/> Other: Bulk Sample	

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
<p>An inspection of Cameco Corp.'s ('Cameco'), Aberdeen camp was completed by Crown-Indigenous Relations and Northern Affairs Canada ('CIRNAC')s, Resource Management Officer, Christine Wilson ('Inspector'). The inspection was a follow-up to ensure compliance with applicable terms and conditions of the water licence no. 2BE-QAM1217.</p> <p>The following report was produced with observations noted by the Inspector in 2017, discussions between Cameco and the Inspector and the observations of the August 11th inspection.</p> <p>PRELIMINARY NOTES</p> <ul style="list-style-type: none"> — In 2017 an inspection of the Turqavik and Aberdeen project's land use permit no. N2015C0036 and water licence no. 2BE-QAM1217 was completed. A final inspection report was issued for the land use permit for the activities on crown land at Qamanarrjuk camp and Arrowhead airstrip. The water licence inspection noted some additional work to be completed at the Aberdeen camp, located on Inuit owned land, prior to a final inspection. — In 2020 Cameco confirmed that the Aberdeen Camp removal was completed and requested a final inspection of the water licence. <p>OBSERVATIONS</p> <ol style="list-style-type: none"> 1. The camp and all associated materials have been removed. 2. Core and core racks remain on site at approximately N64° 23' 37.4", W98° 27' 52.6". 			
SECTION 2	<input type="checkbox"/> Comments (s. __)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s. __)
No instances of non-compliance at this time related to the Nunavut Water Act or the current water licence.			
SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s.3)
Based on the information gathered during the inspection, Field Operations has determined that a final inspection has been completed.			

Licensee or Representative	Inspector's Name
	C. Wilson
Signature	Signature
Date	Date
	November 20th, 2020

Office Use Only: Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---



PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
August 11th, 2020	2BE-QAM1217	Sony DSC-HX50V Cyber shot	RMO Wilson
Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)		
Photo 1	N64° 23' 32.95", W98° 27' 35.03"		



Description:
Aberdeen Camp Area.



Photo No.

Photo 2

Lat/Long (DD.MM.SS.SS, NAD83)

N64° 23' 37.4", W98° 27' 52.6"



Description:

Aberdeen Camp Area.



Photo No.

Photo 3

Lat/Long (DD.MM.SS.SS, NAD83)

N64° 23' 28.53", W 98° 27' 19.43"



Description:

Aberdeen Camp Airstrip