

WATER LICENCE INSPECTION FORM

Original	
Follow-Up	Report

Licensee				Licensee I	Representati	ive				
Strongbow Explo	ration	Inc.		N/A						
Licence No. / Expiry				Represen	tative's Title					
2BE-REG0608				-						
Land / Other Authorizations				Land / Ot	her Authoriz	zations				
N2004C0019										
Date of Inspection				Inspector						
10/07/2014				Eva Pa	aul					
Activities Inspected Camp	Drilling		□ Mining				□ Reclamation □ R		uel Storage	
Roads/Hauling	Other:		Mining		onstruction ther:		Keciamation	Шг	uei Storage	=
Conditions: A - Ac	ceptable		C - Concern	U - Unacce _l	otable	NA –	Not Applicable	NI -	- Not Ins	nected
Water Use	Condition	Comment	Site Condition		Condition	Comment	Haz/Mat Manage		Condition	Comment
Intake/Screen	NA		Water Managen		Α		Storage		NA	
Flow Measure. Device	NA		Culverts / Brid	ges	NA		Spills		Α	1
Source:	NA		Drainage	<u> </u>	Α		Spill Plan		NI	
Water Use:	NA		Erosion / Sedir	ment	Α					
Recirculation (y /n)	NA		Mitigation Me		Α		Administrative			
(77)			Reclamation A		U		Records		Α	
			Materials Stora	age	NA		Reports		Α	
Waste Disposal			Signage	-0-	NA		Plans		Α	
Waste Water	Α		8.18.6				Notifications		Α	
Solid Waste	U		Monitoring				Other			
Hazardous Waste	Α		Sample Collect	ion / Analysis	NA					
				<u> </u>						
*The number in the comments field will correspond with specific comments provided below.										
Samples taken by Inspector: Location(s):										
Yes No										
SECTION 1										
An inspection was conducted on July 10 2014. One camp was inspected and four drill areas; coordinates obtained from annual and										
final reports. The camp was located at and N65 18 55.0 W107 37 55.0. The 2008 drill location (RL-01-08) was inspected, along with										
three earlier drill areas: M-39, M-44, and M-48 (coordinates randomly chosen from the 2004 annual report). Two other camps ("Fly										
camp" (2005) N65 07 39.0 W107 50 05.0 and Musk Camp N65 19 26.0 W107 38 07.0) were inspected by Melissa Joy in 2009. The										
findings are as follows:										
Camp 2 (N65 18 55.0 W107 37 55.0): Tarp noted on shore on NE side of lake. 4 plastic pails noted on the SW side of lake. Small pieces of plastic and burned lumber also noted at site of camp. Core racks are on a hill to the south of the lake.										
RL-01-08: drill collar and debris removed.										
M-44: several holes drill	ed in pro	ximity. C	Collars and ancho	rs left in; deb	is on-site.					
M-48 and M-39: several holes drilled in proximity. Collars and anchors left in; debris on-site.										



Affaires autochtones et Développement du Nord Canada

SECTION 2 Comments	Non-Compliance with Act or Licence	Action Required				
<u>2BE-REG0608</u>						
Part H Item 1: Failure to complete all restoration w	ork prior to the expiry of the licence.					
Part H Item 4: Failure to remove all materials prior	to the expiry of the licence.					
Part H Item 9: Failure to restore drill holes to natur	ral conditions immediately upon completion c	of drilling.				
2BE-REG0406						
Part H Item 5: Failure to carry out progressive recla	amation with respect to drill site reclamation.					
SECTION 3 Comments	Non-Compliance with Act or Licence	Action Required				
Final reclamation of the site is required, including of	drilling activities, before licence cancellation v	will be possible. All drill sites (2004)				
are to be reclaimed. A report detailing the comple	ted work (with photographs) is to be submitt	ed to the Inspector upon final				
reclamation.						
Licensee or Representative	Licensee or Representative Inspector's Name					
- Eva Paul						
Signature Signature						
- Sent electronically						
Date Date						
- 27 August 2014						
APPENDICES: Inspection Photos	Sample Results Other:					
Office Use Only: Follow-up report to be issued by Inspector	r Yes 🗌] No				
CC: Phyllis Beaulieu, Manager of Licensing, NWB						
Erik Allain, Manager of Field Operations, AANDC						

Tracey McCaie, Manager of Land Administration, AANDC

Baba Pedersen, Resource Management Officer, Kitikmeot Region, AANDC

