



## APPENDIX 1: Photos of July 10 2014 Inspection



Figure 1. Tarp noted on NE shore of lake.



Figure 2. Plastic pails noted on SW side of lake, along with plastic and burnt lumber.





Figure 3. White plastic pail and lumber.



Figure 4. Burnt remains of camp.





Figure 5. Core racks visible, some debris in fore-ground.



Figure 6. One of several drill sites left un-reclaimed at M-44.





Figure 7. Drill casing/anchor and debris near M-44.



Figure 8. Un-reclaimed drill sites near M-48.