



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee			Licensee Representative		
Forum Uranium Corp.			Anthony Williamson		
Licence No. / Expiry			Representative's Title		
Unlicensed Inspection			Project Manager		
Land / Other Authorizations					
2BE-SCH0712 (Expired)			N2007C0017		
Date of Inspection			Inspector		
18/07/2014			Justin HACK		
Activities Inspected					
<input checked="" type="checkbox"/> Camp		<input checked="" type="checkbox"/> Drilling		<input type="checkbox"/> Mining	
<input type="checkbox"/> Roads/Hauling		<input type="checkbox"/> Other:		<input type="checkbox"/> Construction	
				<input type="checkbox"/> Reclamation	
				<input type="checkbox"/> Fuel Storage	
Conditions: A - Acceptable C - Concern U - Unacceptable NA – Not Applicable NI – Not Inspected					
Water Use		Condition	Comment	Site Conditions	
Intake/Screen		NA		Water Management Structures	
Flow Measure. Device		NA		Culverts / Bridges	
Source:		NA		Drainage	
Water Use:		NA		Erosion / Sediment	
Recirculation (y /n)		NA		Mitigation Measures	
				Reclamation Activities	
				Materials Storage	
Waste Disposal				Signage	
Waste Water		NA			
Solid Waste		NA		Monitoring	
Hazardous Waste		NA		Sample Collection / Analysis	
*The number in the comments field will correspond with specific comments provided below.					

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Background			
In 2011, Forum Uranium purchased a camp located at Thom Lake from Tanqueray Resources and has moved this camp to the east side of Judge Sissons Lake (N64 16 32.2 W97 32 06.4). Forum Uranium Corp. has an expired water licence but is undergoing a water licence renewal application in preparation for future exploration work.			
Observations			
All activities were conducted on Kivalliq Inuit Association land. This camp consisted of approximately 13 canvas sided tents, a wooden cook shack, storage facilities, snow machines, and two fuel caches containing approximately 400 barrels of fuel in secondary containment. The condition of the fuel cache was satisfactory and a rain drain filter was attached at the lowest section of the berm to filter any excess water.			
Under water licence 2BE-SCH0712, Forum Uranium is not permitted any camp installations or operations; however, this camp is inactive. At the time of the inspection, there was no evidence that water was used or waste was deposited to water.			
During the inspection, 5 drill sites under the expired licence 2BE-SCH0712 were inspected (RD7-01, RW-01, GR-01, BD-01, BD-02). All drill sites appear to have been managed satisfactory as outlined in the licence except site BD-02. At this site, a drill collar was not cut and the hole was not permanently sealed. As part of remediation activities, drill collars must be removed and the holes must be capped with a permanent seal.			
SECTION 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required

Inspector's Name
Justin Hack
Signature
Date
August 20, 2014