



Tahera Diamond Corporation
Exploration Office
#7-68 Schooner St
Coquitlam BC V3K 7B1

August 30, 2007

Attn. Phyllis Beaulieu

Manager of Licensing
Nunavut Water Board
PO Box 119
Gjoa Haven, Nunavut
X0B 0J0
(867) 360-6338

Summary Report for 2006 Rockinghorse Property

During 2006 no work was based out of Tak camp. No drilling work was carried out on the property. A minimal amount of work was done on the property, based out of Muskox Camp, including soil sampling and ground geophysics. Therefore the water use for both industrial and domestic purposes was zero. The camp was inspected during the year and no problems were found.

The following maps and documents should be considered in the reading of this document.

- Rockinghorse Final Abandonment and Restoration Plan
- Rockinghorse Spill Contingency Plan
- Detailed map of Tak Camp

NWB Annual Report

Year being reported:

2006

**License
No:**

--

Issued Date:

Expiry Date:

Project Name: **Rockinhorse**

Licensee: Tahera Diamond Corporation

Mailing Address: #7-68 Schooner St Coquitlam BC V3K 7B1

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management

Water Source(s):

Lake adjacent to camp

Water Quantity:

0 cu. m/day

0 cu. m/day

Quantity Allowable Domestic (cu.m)

Actual Quantity Used Domestic (cu.m)

Quantity Allowable Drilling (cu.m)

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:

(as reported to the Spill Hot-line)

Date of

Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No unauthorized discharges occurred

Revisions to the Spill Contingency Plan

Additional Details:

Revisions to the Abandonment and Restoration Plan

Progressive Reclamation Work Undertaken

.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Additional Details:

Any additional comments or information for the Board to consider

Date Submitted:

August 31, 2007

**Submitted/Prepared
by:**

Ferg McDonnell

Contact Information:

Tel: 604 519 1977

Fax: 604 519 1978

email: fmcdonnell@tahera.com

GPS Coordinates for water sources utilized

Source Description	Latitude			Longitude		
	Deg °	Min ,	Sec ,	Deg °	Min ,	Sec ,

