



Tahera Diamond Corporation  
Exploration Office  
#7-68 Schooner St  
Coquitlam BC V3K 7B1

August 30, 2007

**Attn. Phyllis Beaulieu**

Manager of Licensing  
Nunavut Water Board  
PO Box 119  
Gjoa Haven, Nunavut  
X0B 0J0  
(867) 360-6338

**Summary Report for 2007 Rockinghorse Property**

This summary report should be read in conjunction with the tables "Rockinghorse 2007 Annual Report Tahera".

During 2007 a Winter/Spring Exploration Program was completed on the Rockinghorse Property. The camp was not utilized during the summer at all. The camp was opened in early February and a Diamond Drilling Operation began in early March. A small geophysics program also ran concurrently with the drilling operation. The camp has been inspected by Tahera personnel during the summer of 2007 and no problems were found.

Water was used for domestic purposes at Tak Camp. Domestic uses include: water required for cooking, cleaning, showers, drinking, etc and averaged (estimated) 5 cubic metres per day. The camp facilities were in operation for approximately 110 days and therefore total water usage is estimated to be 550 cubic metres. The water was sourced from the lake which is proximal to Tak Camp. The pump used is a ½ HP 115 V pump. The water intake is equipped with a mesh screen with a screen size less than 2.54 mm to prevent the entrapment of fish as per DFO guidelines. Water was filtered with a particulate filtration system as well as a UV filter.

At the Anuri Kimberlite Pipe, water was used for industrial purposes as part of a normal diamond drilling operation. The drill ran for approximately 76 days, and using an estimated 40 cubic metres per day, totalled 3040 cubic metres for the program.

Sewage and waste was managed in accordance with the plan submitted in the Remote Camp Questionnaire. "Pacto" brand latrines are installed in the camp and human waste was burnt daily in the camp incinerator. Grey water was disposed in the sump next to the kitchen. A grease trap was installed in the kitchen and this was cleaned thoroughly at the end of the program. The sump is sealed and insulated and was monitored daily. There

were no operational problems. Burnable waste was incinerated in camp. Non-burnable material, including incinerator residues, was backhauled to Yellowknife. Scrap metal, aerosols, batteries, as well as bulky items were included in the non-burnable material. Waste oil was removed to the Jericho minesite where it will eventually be hauled off site with a waste manifest as per EPS procedures.

Drill cuttings and drill water from the diamond drill were pumped to a suitable location near the drill sites. Maps are provided.

The following maps and documents should be considered in the reading of this document.

- Rockinghorse Final Abandonment and Restoration Plan
- Rockinghorse Spill Contingency Plan
- Detailed map of Tak Camp
- Detailed map of Anuri Drill site

**NWB Annual Report**

**Year being reported:**

2007

**License  
No:**

**Issued Date:**

**Expiry Date:**

**Project Name:**

**Rockinghorse**

**Licensee:**

Tahera Diamond Corporation

**Mailing Address:**

#7-68 Schooner St Coquitlam BC V3K 7B1

**Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between two entities, if applicable):**

**General Background Information on the Project (\*optional):**

**Licence Requirements: the licensee must provide the following information in accordance with**

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management**

Water Source(s):	Lake adjacent to camp	
Water Quantity:		Quantity Allowable Domestic (cu.m)
	5 cu. m/day	Actual Quantity Used Domestic (cu.m)
		Quantity Allowable Drilling (cu.m)
	40 cu. m/day	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

All grey water from domestic use was contained in a grey water sump.

Additional Details:

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

**Revisions to the Spill Contingency Plan**

Additional Details:

## **Revisions to the Abandonment and Restoration Plan**

## **Progressive Reclamation Work Undertaken**

All sites that were drilled during the 2007 drilling program have been inspected and cleaned up.

## **Results of the Monitoring Program including:**

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Additional Details:

## **Results of any additional sampling and/or analysis that was requested by an Inspector**

Results of 2007 water testing are pending.

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported**

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Additional Details:

**Any additional comments or information for the Board to consider**

**Date Submitted:**

August 31, 2007

**Submitted/Prepared by:**

Ferg McDonnell

**Contact Information:**

**Tel:** 604 519 1977

**Fax:** 604 519 1978

**email:** [fmcdonnell@tahera.com](mailto:fmcdonnell@tahera.com)

### GPS Coordinates for water sources utilized

Source Description	Latitude			Longitude		
	Deg °	Min '	Sec "	Deg °	Min '	Sec "
Lake (camp)	66	35	35	113	5	14
Lake (drilling)	66	33	8	112	57	8

### GPS Locations of areas of waste disposal

Location Description (type)	Latitude			Longitude		
	Deg °	Min '	Sec "	Deg °	Min '	Sec "
sump(camp)	66	35	34	113	5	14
Sump(drill)	66	33	21	112	57	21