

WATER USE INSPECTION REPORT

Date: August 10, 2009	Licensee Rep. (Name/Title): None
Licensee: Titan Uranium.	Licence No: 2BE-THE0813

WATER SUPPLY

Source(s): Itsa Lake.		Quantity used: -None	
Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected			
Intake Facilities: NA	Storage Structure: NA	Treatment Sys: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: Camp is closed at this time. No water consumption on site.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): None- camp is closed at the time of inspection

Grey Water: None

Natural Water Body: NA	Continuous Discharge (land or water): NA		
Seasonal Discharge: NA	Wetlands Treatment: NA	Trench: NA	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: NA
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NA	A&R Plan: NA
Periods of Discharge: NA.	Effluent Discharge Rate: NA	

Comments: Camp is closed at this time

Solid Waste: None . Camp is closed. Materials have been consolidated into piles around camp.

Landfill: NA	Burn & Landfill: NA	Other: None
--------------	---------------------	-------------

Comments: Camp is closed at this time.

FUEL STORAGE: 3 Secondary Containment caches. Leaks obvious in berms.

Waste Oil Storage: None noted

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: U	Water within Berms: U	Evidence of Leaks: U
Drainage Pipes: U	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: U	

Comments: Secondary containment noted at Camp. Drums within the cache are leaking. Water has built up within the containment. 1 side of each of the two containment berms were not supported and laying flat. Fuel and oil noted within the containment. Maintenance and monitoring are required.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator: Titan Uranium.	
0		INAC: None	
Signs Posted	SNP: None		Warning: U
Records & Reporting: None			
Geotechnical Inspection: N/A			

Non-Compliance of Act or Licence: A care and maintenance plan is required for the Itsa Lake camp. Fuel storage on site was found to be leaking into the secondary containment. Water has built up in the containment and threatens integrity of the berms. Licensee is required to take such actions as are required to prevent the release of hydrocarbons into the environment.

A.Keim

Inspector’s Name

Sent by E-mail

Inspector’s Signature