## Bonito Capital Corp.

(a subsidiary of Elgin Mining Inc.)

5 November 2013

Ms. Phyllis Beaulieu Manager of Licensing **Nunavut Water Board** P.O. Box 119 Gjoa Haven, NU **X0B 1J0** 

Dear Ms. Beaulieu

RE: 2013 Annual Geotechnical Inspection – Ulu Gold Project, Nunavut Ulu Gold Project, Nunavut, License Number 2BM-ULU0914

Please find attached 2013 Geotechnical Inspection Report, completed by SRK Consulting, to fulfil part D, item 10 of our water licence.

There are no issues requiring immediate attention identified in the report. The exposed and/or damaged liners will be covered and/or repaired in the 2014 summer season.

If you have any questions regarding the above, please do not hesitate to contact me.

Sincerely, **Bonito Capital Corp.** 

George Friesen Manager of Technical Services

CC: Patrick Downey, CEO of Elgin Mining Inc.

2BM-ULU0914

070213-2BM-ULU0914-MONTHLYREPORTJUNE2013 This file is produced electronically with 2 pages