



WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Hamlet of Chesterfield Inlet	Roy Mullins
Licence No. / Expiry	Representative's Title
3BM-CHE1523	Senior Administrative Officer
Land / Other Authorizations	Land / Other Authorizations
	--
Date of Inspection	Inspector
July 31 st 2017	Atuat Shouldice
Activities Inspected	
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input checked="" type="checkbox"/> Other: Municipal
	<input checked="" type="checkbox"/> Other: Hazardous waste
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.____)	<input type="checkbox"/> Action Required (s.____)
Summary			
On July 31 st , 2017 Indigenous and Northern Affairs Canada's Water Resource Officer, Atuat Shouldice completed an annual Community inspection of the hamlet of Rankin Inlet permit 3BM-CHE1523. The inspection was conducted with Megan Lusty, Municipal Planning Engineer with the Government of Nunavut.			
SECTION 2			
<input checked="" type="checkbox"/> Comments (s.____)			
<input type="checkbox"/> Non-Compliance with Act or Licence (s.2)			
<input type="checkbox"/> Action Required (s.____)			
Observations			
Landfill			
The landfill was organized and a lot of work has gone in to segregating different material. No waste was observed leaving the landfill footprint.			
Water			
The water meter at the lake was not working as it was damaged during resupply. The Hamlet is reminded that proper water use records are a condition of the water license and that the water meter should be fixed or replaced as soon as possible. It was also observed that the supply line to the water reservoir has some damage to it and is recommended to be replaced.			
Waste metal dump			
A lot of work has been done in the waste metal dump to segregate bulk items remove hazardous waste. No waste was observed leaving the footprint of the metal dump.			
Hazardous waste			
Hazardous waste is now being collected and stored in seacans. A series of seacans are being used at the landfill to store old batteries so they do not leach into the environment. Waste oil drums are now being capped and palletized and were in the process of being stored in seacans during the inspection to prevent them from being exposed to the environment.			
Sewage disposal			
No issues noted with sewage drop off site and wet land.			
SECTION 3			
<input checked="" type="checkbox"/> Comments (s.____)			
<input type="checkbox"/> Non-Compliance with Act or Licence, (s.____)			
<input checked="" type="checkbox"/> Action Required (s.3)			
The Hamlet of Chesterfield Inlet has done a lot of work to come into compliance with the water license requirements. The inspector would like the hamlet to focus on record keeping moving forward and as a first step in that direction; the water meter should be fixed or replaced as soon as possible.			

Licensee or Representative	Inspector's Name
	WRO A Shouldice
Signature	Signature
Date	Date
	4/19/2018

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

cc. Erik Allain, Manager Field Operations, INAC