

# **Water Licence Inspection Report**

⊠Original	
□Follow-Up	Report

Orginization	Representative			
Hamlet of Chesterfield Inlet	Paul Bosetti			
Authorization No. / Expiry	Representative's Title			
3AM-CHE2333/ December 19 <sup>th</sup> 2033	Senior Administrative officer			
Inspection Date	Inspector			
July 17 <sup>th</sup> 2024	Atuat Shouldice			
Other Authorization/s				
Activities Inspected				
☐ Camp, Commercial ☐ Drilling ☐ Mining ☐ Construction ☐ Reclamation ☐ Fuel Storage ☐ Roads/Hauling ☐ Winter Hauling				
☐ Camp, Private ☑ Other Municipal				

#### **Section 1 Comments**

On July 17<sup>th</sup> 2024 an inspection was conducted of Water Licence 3BM-CHE2333 (Licence) Hamlet of Chesterfield Inlet. Resource Management Officer Atuat Shouldice (Inspector) for Crown-Indigenous Relations and Northern Affairs Canada (CIRNAC) was accompanied by Megan Muckpah-Gavin Government of Nunavut, Community and Government Services(CGS). Sampling was conducted by both parties at compliance points identified under licence.

#### -Landfill and domestic waste

Open burning of municipal waste shall be conducted only in accordance with the Government of Nunavut's Environmental Guideline for the Burning and Incineration of Solid Waste (2012), at the designated location at the Solid Waste Disposal Facility, during inspection conditions were being followed under water licence conditions Part E item 8.

#### -Hazardous waste storage

The Hamlet has been colleting discarded batteries, empty propane, waste oil and storing items in shipping containers. The hamlet is following Licence conditions item Part E item 7.

### -Sewage Disposal Facility (SDF)

Sewage is discharged in to one of two Holding Cells used to store and pretreat Sewage before discharge into the Wetland Area. During the inspection the discharge point closest to landfill was not being used because it was full of sludge. This non-compliant with the Operations and Maintenance Plan


#### -Water Supply Facility

Water is pumped from First Lake (Puiqsuk Lake), during inspection water resupply was scheduled to start until the following month.

## -Administrative

As of October 21st, 2024, The 2023 annual report was not submitted to the Nunavut Water Board.







## **Section 2 Non-Compliance with**

Non-Compliance with the Licence:

o Part B Item 1: Failure to submit annual report

## **Section 3 Action Required**

The Licensee shall:

- $\circ\quad$  Remove sludge from SDF as identified in the Inspection
- o Submit information to CGS to allow submission of the annual report by the 21st of November, 2024.

## Section 4 Other

Licensee or Representative	Inspector's Name
Paul Bosetti	Atuat Shouldice
Signature	Signature Sharling
Date	Date

Office Use Only:	Follow-up report to be issued by Inspector	☐ Yes ☐ No

PHOTO LOG			
Date:	Authorization Number:	Camera/Model:	Inspector
Wednesday, July 17, 2024	3AM-CHE2333	Samsung S21	Atuat Shouldice
Photo No.		Lat/Long (DD.MM.SS.SS, NAD83)	
Photo #1		N63 20' 43.91" W90 45' 6.89"	
05 1856 1 201 Marc 27 16 177			
	and the second of the second o		
Description:			



Landfill photo of segragated locations for opening burning, demestic waste, and hazardous waste storage.

















