



Canada NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130 FAX: (867) 873-6924 EMAIL: spills@gov.nt.ca

										RE	PORT LINE USE ONLY	
Α	REPORT DATE: MONTH – DAY – YEAR December 27, 2010			REPORT TIME 1:00 PM		☑ ORIGINAL SPILL REPORT, OR				REP	ORT NUMBER	
В	OCCURRENCE DATE: MONTH – DAY – YEAR Discovered on December 27, 2010			OCCURRENCE TIME 8:30 AM		☐ UPDATE # TO THE ORIGINAL SPILL REPORT			REPORT			
О	LAND USE PERMIT NUMBER (IF APPLICABLE)				WATER LICENCE NUMBER (IF APPLICABLE)							
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM Iqaluit			MITHE NAMED LOCATION			REGION ☐ NWT ☑ NUNAVUT ☐ ADJACENT JURISDICTION OR					
Е	LATITUDE DEGREES MINUTES SECONDS			LONGITUDE DEGREES MINU			UTES SECONDS					
F				RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION P.O. Box 460 Idaluit. NU XOA 0H0								
G	ANY CONTRACTOR INVOLVED NA			CONTRACTOR ADDRESS OR OFFICE LOCATION NA								
Н	PRODUCT SPILLED Fuel			QUANTITY IN LITRES, KILOGRAMS OR CU			JBIC METRES U.N. NUME			IBER		
• •	SECOND PRODUCT SPILLED (IF APPLICABLE) NA			QUANTITY IN LITRES, KILOGRAMS OR C			SUBIC METRES U.N. NUM			/IBER		
-	SPILL SOURCE Fuel Tank at Apex Garage		-	SPILL CAUSE Equipment malfunction				AREA OF CONTAMINATION IN SQUARE METRES 10 sq. meters				
٦	FACTORS AFFECTING SPILL OR RECOVERY Direction required			DESCRIBE ANY ASSISTANCE REQUIRED Direction required				HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT				
Κ	The heating system at the City's Apex Garage has been malfunctioning for the last 3-4 days. During this time, a temporary fuel supply has been installed indoors to allow the system to function. On December 27, 2010 at 8:30 am, the Acting Utilidor Foreman was at the garage to let in a contractor to fix the heating system. At this time, it was noticed that a fuel spill of approximately 100 L had occurred on the exterior fuel tank. It appears that a check valve on a secondary motor failed and that the fuel from the temporary supply was pumped in to the main exterior tank. Furthermore, it appears that the containment section on the main tank was compromised resulting in the spill. The extent of the spill is minimal and the fuel has collected under the tank and up to 2 meters from the tank in the surrounding area. The presence of snow and cold weather has helped in keeping the affected area to a minimum. Barricades have been placed around the fuel tank. The City requests that direction be given on the recovery process.											
L	REPORTED TO SPILL LINE BY Arif Savani		POSITION A/Manager PW				LOCATI Iaaluit	ATION CALLING FROM uit		TELEPHONE 867-222-4436		
М	ANY ALTERNATE CONTACT		POSITION	E	MPLOYER	,	ALTERN	LTERNATE CONTACT LOCATION		ΓΙΟΝ	ALTERNATE TELEPHONE	
REPORT LINE USE ONLY												
N	RECEIVED AT SPILL LINE BY		POSITION Station operator	E	MPLOYER		LOCATION CALLE Yellowknife, N				REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY ☐ EC ☐ CCG ☐ GNWT ☐ GN ☐ ILA ☐ INAC		I ILA 🗌 INAC 🗌 NEB 🔲	EB ☐ TC SIGNIFICANCE ☐ MINOF		INOR 🗆	I IMAJOR I IUNKNOWN I			FILE ST CLOSE	TATUS ☐ OPEN ☐ ED		
AGENCY		CONTACT NAME		C	CONTACT TIME REMA			MARKS				
LEAD AGENCY												
FIRST SUPPORT AGENCY												
SECOND SUPPORT AGENCY												
THIRD SUPPORT AGENCY												