



Northwest Serifories Canada NT-NU SPILL REPORT

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130 FAX: (867) 873-6924 FMAIL · spills@gov nt ca

len	mones runarat		OIL, GASOLINE	E, CHEMICAL	S AND OTHER HA	AZARD0	US MATERIALS			EMAIL: Spills@gov.nica	
	Τ					1			REI	PORT LINE USE ONLY	
Α	REPORT DATE: MONTH – DAY – YEAR 02-09-2011			10:00		⊠ OR	☑ ORIGINAL SPILL REPORT, OR		REPORT NUMBER		
В	OCCURRENCE DATE: MONTH – DAY – YEAR 02-08-2011				OCCURRENCE TIME 17:00		☐ UPDATE # TO THE ORIGINAL SPILL REPORT				
С	LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER			(IF APPLICABLE)				
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FRO Lift Station # 2, Near Manhole # 30 Iqaluit, Nunavut						REGION ☐ NWT ☑ NUNAVUT ☐ ADJACENT JURISDICTION OR				
Е	LATITUDE DEGREES MINUTES SECONDS			LONGITUDE DEGREES MINUTES SECONDS							
F	RESPONSIBLE PARTY OR VESSEL NAME City of laaluit			RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Idaluit. NU. X0A 0H0							
G	ANY CONTRACTOR IN none	VOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION							
Н	PRODUCT SPILLED Sewage			QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 200 litres				U.N. NUMBER			
	SECOND PRODUCT SPILLED (IF APPLICABLE) none			QUANTITY IN LITRES, KILOGRAMS OR CUBIC MET			BIC METRES	U.N. NUMBER			
I	SPILL SOURCE Sewage Lift Station		SPILL CAUSE Electrical Breakers tripped			AREA OF 6 M2	F CONTAMINATION IN SQUARE METRES				
J	FACTORS AFFECTING SPILL OR RECOVERY Snow and ice			DESCRIBE ANY ASSISTANCE REQUIRED none			HAZARD:	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT none			
	ADDITIONAL INFORMA	ATION, COMMENTS, A	CONTAIN, RECOVE	R OR DISF	POSE OF SPILLED	PRODUCT A	AND CC	ONTAMINATED MATERIALS			
K	electrical breakers neede to be reset. once the breakers were reset, the sewage levels returned to normal and all appeared to be working properly. A loader and dump truck supplied by the city cleaned up any sewage that was spilled on the snow around the manhole and it was hauled to the sewage lagoon for disposal. An electrical contractor was called in to check and repair the high level warning system at the sewage lift station on the morning of Feb 09. This system appears to be working correctly now. The spill of approximately 200 litres was contained by the snow around the manhole, and was easily scraped up with the loader. Regular checks of this area will continue to be done during peak sewage flow times daily.										
L	REPORTED TO SPILL LINE BY Frank Ford		POSITION PW Superinter	I	EMPLOYER Citv of laaluit		LOCATION CALLIN			TELEPHONE 867-979-5653	
M	ANY ALTERNATE CONTACT Rob Hogan		POSITION Utilidor Forema		EMPLOYER City of Igaluit		ALTERNATE CONTACT LOCATION 1554D		TON	ALTERNATE TELEPHONE 867-222-2941	
REPORT LINE USE ONLY											
Ν	RECEIVED AT SPILL LINE BY		POSITION Station operator				LOCATION CALLE Yellowknife, N			REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY EC CCG GNWT GN ILA INAC NE			B TC SIGNIFICANCE MINOR MAJOR			MAJOR 🗌 UNKI	NOWN FILE STATUS OPEN CLOSED				
AGENCY CONTACT NAME					CONTACT TIME		REMARKS				
LEAD AGENCY											
FIRST	SUPPORT AGENCY										
SECON	ND SUPPORT AGENCY										
THIRD SUPPORT AGENCY											