



Canada NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130 FAX: (867) 873-6924 EMAIL: spills@gov.nt.ca

										REI	PORT LINE USE ONLY	
Α	REPORT DATE: MONTH – DAY – YEAR 10-03-2011			REPORT TIME 13:00		⊠ OR	☑ ORIGINAL SPILL REPORT, OR				ORT NUMBER	
В	OCCURRENCE DATE: MONTH – DAY – YEAR 10-02-2011			OCC 16:0	URRENCE TIME 00	_	□ UPDATE# TO THE ORIGINAL SPILL RI					
О	LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER			R (IF APPLICABLE)					
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FRO Manhole #09 City of Iqaluit			OM THE NAMED LOCATION			REGION ☐ NWT ☑ NUNAVUT ☐ ADJACENT JURISDICTION OR					
Е	LATITUDE DEGREES MINUTES SECONDS			LONGITUDE DEGREES MINU			JTES SECONDS					
F	RESPONSIBLE PARTY OR VESSEL NAME City of laaluit			RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Igaluit. NU. XOA 0H0								
G	ANY CONTRACTOR IN		cc	CONTRACTOR ADDRESS OR OFFICE LOCATION								
Η	PRODUCT SPILLED Sewage			QUANTITY IN LITRES, KILOGRAMS OR CU approx. 8000 I.			JBIC METRES U.N. NUME			IBER		
•	SECOND PRODUCT SPILLED (IF APPLICA none		E) QL	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES U.N. NU					U.N. NUM	JMBER		
	SPILL SOURCE Manhole #09		_	SPILL CAUSE Partially blocked sewage main				AREA OF CONTAMINATION IN SQUARE METRES 100 m2				
J	FACTORS AFFECTING SPILL OR RECOVERY run-off from snow melt		DE no	NY ASSISTANCE REQUIRED			HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT none			ROPERTY OR EQUIPMENT		
K	On October 02, 2011 it was noticed that Manhole #09 was starting to run over. Two vacuum sewage trucks from the City of Iqaluit were immediately called to pump out the manhole. Once the manhole was pumped out the trucks stayed on site to monitor while the City Utilidor crew could blast the sewage main from the down stream manhole #08. It was noted that the main was partially clogged with rags and pieces of wood. The sewage that spilled over manhole #9 ran down the ditch area, and was confined to the ditch area which then drained directly into the top of manhole #08 down stream which contained an open sewage main. There was continual flow of runoff taking this same path from the melting snow. The affected ditch was scraped with a loader provided by the city, and fresh sand was used to cover the inside of the ditch also supplied by the City of Iqaluit. The affected material (approximately 10 m3) was hauled to the lagoon for disposal. The cause was contributed by extremely high flow due to snow melt run-off, normal high volumes on Sundays, and a partial blockage of the main by rags and wood which was removed.											
L	REPORTED TO SPILL LINE BY Frank Ford		POSITION PW. Superintendent				LOCATION CALLING FROM 1554D			TELEPHONE 867-979-5653		
М	ANY ALTERNATE CONTACT Jeff Getz		POSITION Utilidor Maintainer				NTACT LOCATION		ALTERNATE TELEPHONE 867-222-3263			
REPORT LINE USE ONLY												
N	RECEIVED AT SPILL LINE BY		POSITION Station operator		MPLOYER			ON CALLED /knife, NT			REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY EC CCG GNWT GN ILA			ILA INAC NEB	TC S	SIGNIFICANCE MINOR MAJO		MAJOF	R 🗆 UNKNO	NKNOWN FILE ST CLOSE		TATUS OPEN D	
AGENCY CONT		CONTACT NAME	ONTACT NAME		CONTACT TIME REMA		REMARI	MARKS				
LEAD AGENCY												
FIRST SUPPORT AGENCY												
SECOND SUPPORT AGENCY												
THIRD SUPPORT AGENCY												