

Project No. 03-4302			Resolute Bay Utildor Repair							
		Laterals yet to be completed								
5 Housing Association Units										
	No.	Lin ft	Tank	Curb Boxes Required?						
Adam Kalluk	98	105	On a tank	No box required, unless damaged during contract						
Janice Kalluk	85	50	On a tank	No box required						
Anna Nungaq	104	57	On a tank	Box required						
Matthew Nungaq	93	53	N/A	Box required - is on a shared water line from Manhole AV 7						
Simon Idlout	92	44	On a tank	Box required						
7 Private Units										
	No.	Lin ft								
RCMP	591	53		Box required. At present is on a shared waterline from AV 7						
RCMP	91	140		Box required. At present is feeding off Housing Unit # 105						
S. Ulayuruluk	114	62		Box required. At present is feeding off Staff Unit 37-011						
I. Kalluk	74	53		Box required. At present is on shared waterline from AV 7						
T. Manik	A2 or 192	63		Box required. At present is on shared waterline from AV 7						
P. Kalluk	75	56		Box required. At present is on shared waterline from AV 27						
P. Attagootak	Staff Unit 37-011	68	Box required. Has been restored with a small leak (replacement required)							