

| | | | | | | | | | | |
|-----------------------------|-------------------|------------------------------|--|---|--|--|--|--|--|--|
| Project No. 03-4302 | | | Resolute Bay Utildor Repair | | | | | | | |
| | | | | | | | | | | |
| | | Laterals yet to be completed | | | | | | | | |
| | | | | | | | | | | |
| 5 Housing Association Units | | | | | | | | | | |
| | No. | Lin ft | Tank | Curb Boxes Required? | | | | | | |
| Adam Kalluk | 98 | 105 | On a tank | No box required, unless damaged during contract | | | | | | |
| Janice Kalluk | 85 | 50 | On a tank | No box required | | | | | | |
| Anna Nungaq | 104 | 57 | On a tank | Box required | | | | | | |
| Matthew Nungaq | 93 | 53 | N/A | Box required - is on a shared water line from Manhole AV 7 | | | | | | |
| Simon Idlout | 92 | 44 | On a tank | Box required | | | | | | |
| | | | | | | | | | | |
| 7 Private Units | | | | | | | | | | |
| | No. | Lin ft | | | | | | | | |
| RCMP | 591 | 53 | | Box required. At present is on a shared waterline from AV 7 | | | | | | |
| RCMP | 91 | 140 | | Box required. At present is feeding off Housing Unit # 105 | | | | | | |
| S. Ulayuruluk | 114 | 62 | | Box required. At present is feeding off Staff Unit 37-011 | | | | | | |
| I. Kalluk | 74 | 53 | | Box required. At present is on shared waterline from AV 7 | | | | | | |
| T. Manik | A2 or 192 | 63 | | Box required. At present is on shared waterline from AV 7 | | | | | | |
| P. Kalluk | 75 | 56 | | Box required. At present is on shared waterline from AV 27 | | | | | | |
| P. Attagootak | Staff Unit 37-011 | 68 | Box required. Has been restored with a small leak (replacement required) | | | | | | | |