
APPENDIX B

PHOTOS



Photo 1. Substrate of north shoreline.



Photo 2a and 2b. Substrate of south shoreline.




Photo 3. Path of outlet stream over large cliff. Photo taken from base of cliff.




Photo 4. Path of outlet stream through mossy area at base of large cliff. Photo taken from bay.




Photo 5. Cobble/boulder substrate at shoreline of Telik Inlet.