

# WATER LICENCE INSPECTION FORM

☑ Original☑ Follow-Up Report

Licensee		Licensee Repre	sentativ	re					
Hamlet of Cape	Dorset		Eric Langdon						
Licence No. / Expiry			Representative's Title						
3BM-CAP0810	(expired)		Mechanic						
Land / Other Authorization	ns								
None									
Date of Inspection			Inspector						
July 26, 2015			Justin HACK						
Activities Inspected  ☐ Camp/Municipality ☐ Roads/Hauling	Drilling Other:	☐ Mining	ing Construction Reclamation Cother:		Fuel Storage	Fuel Storage			
Conditions: A -	Acceptable	C - Concern	U – Unacceptab	le	NA – Not Applicable	NI – Not Ins	ected		
Water Use	Condition	Comment Site Condition	S	Condit ion	Comme Haz/Mat Management	ent Condition	Comment		
Intake/Screen	А	Water Manage	ement Structures	U	Storage	А			
Flow Measure. Device	e A	Culverts / Brid	ges	Α	Spills	А			
Source:	Α	Drainage		U	Spill Plan	А			
Water Use:	Α	Erosion / Sedir	Erosion / Sediment						
Recirculation ( y /n)	NA	Mitigation Me	asures	Α	Administrative				
		Reclamation A	ctivities	Α	Records	NA			
		Materials Stora	age	Α	Reports	NI			
<b>Waste Disposal</b>		Signage		Α	Plans	NI			
Waste Water	U				Notifications	А			
Solid Waste	U	Monitoring			Other				
Hazardous Waste	Α	Sample Collect	cion / Analysis	NI					
:	*The number	in the comments field w	ill correspond with	specif	fic comments provided below.				
Samples taken by Insp	pector:	Location(s):	Location(s):						
☐ Yes ⊠ No									
SECTION 1									

# **Inspectors Statement**

On July 26 2015, a water licence inspection was conducted at the Hamlet of Cape Dorset, Qikiqtani Region, Nunavut. Sites inspected included the New Lagoon (uncommissioned), the Emergency Lagoon, the Three-Tier Lagoon, the Solid Waste Disposal Facility, the Metal Storage Area and the Water Distribution Facilities.

#### **Background**

The Hamlet of Cape Dorset has an expired licence for Municipal Undertakings for the use of 192 cubic meters of water per day and for the deposit of waste.

AANDC is working with the community to upgrade and replace municipal water and waste water infrastructure to maintain essential services and mitigate non-compliance through voluntary compliance with the expired licence as required in Section 46 of the Act.

Community and Government Services has been helping the Hamlet of Cape Dorset renew the licence since 2010.

In the interim, immediate risks related to water and waste disposal will be managed using an Inspector's Directions until a Water Licence is issued. A direction related to the breached Three-Tier Lagoon was sent to the Hamlet of Cape Dorset on July 29, 2015.

# Inspection

## Water Use and related structures:

- 1. Water is being withdrawn from the T-Lake as approved in the expired Water Licence.
- 2. In 2014, the Hamlet of Cape Dorset withdrew approximately a total of 54,723m<sup>3</sup> of water and is withdrawing water at approximately the same rate in 2015.
- 3. Due to the distance between T-Lake and the Water Treatment and Storage Facility, the intermittent flow of the water line and issues with the heat trace, the water line is freezing. The Hamlet is finding solutions to this problem in the interim.
- 4. Water withdrawal records were inspected and were up-to-date.

#### **Three Tier Lagoon and Emergency Lagoon**

5. At the time of the inspection, the berm wall of the third cell suffered a significant failure due to frozen culverts within the facility and overloading due to surface run-off.





- 6. An Inspector's Direction was issued to the Hamlet of Cape Dorset to undertake immediate remedial works on the facility to ensure the facility is working more effectively.
- 7. The unused Emergency Lagoon will be used while remedial works occur on the Three-Tier Lagoon.
- 8. The Three-Tier Lagoon is significantly undersized to effectively treat the sewage in the Hamlet and it is imperative that the 2007 Lagoon is commissioned as soon as possible.

### 2007 Lagoon

- 9. The facility still has not been commissioned and water continues to leak out of the berm.
- 10. It is recommended that an Engineer inspect this Facility and determine if it is appropriate for use.

#### **Solid Waste Facility:**

- 11. Fencing around the Solid Waste Disposal Facility was windblown on the western edge but the Hamlet was actively fixing this concern
- 12. As part of the operation of this facility, open burning is a common practice. I have concern with this practice because, due to changing watercourse patterns, an active stream flows through the landfill. Samples were taken downstream of this facility to understand which contaminates are entering water.
- 13. As a temporary solution to this, the Hamlet has agreed to divert the water course around the Solid Waste Facility to minimize surface water intrusion and leachate generation. The Licensee has agreed to address this issue by September 30, 2015. Photos to be provided upon completion.

#### **Metal Storage Area**

- 14. The community is segregating and storing metals within the Metal Storage Area.
- 15. Batteries are being stored in a contained sea can in anticipation for transportation to a southern disposal facility.
- 16. Water flows though the facility and there is concern that contaminates are leaching into this watercourse. The Hamlet has provided a plan on a solution to divert the watercourse around the facility to minimize surface water intrusion and leachate generation.

#### **Hazardous Waste:**

17. Some hazardous waste and batteries are being segregated in the Metal Storage Area. The materials are being stored sufficiently away from any watercourses and within sea cans.

#### Reports/Records:

SECTION 2

18. Records for Water Use were in good order.

Comments

19. Issues related to Part H (Monitoring Program) of the Licence will be addressed during the next Water Licence Compliance Working Group.

Non-Compliance with Act or Licence

**Action Required** 

	•		•
Click here to enter text.			
Inspector's Name			
Justin Hack			
Signature			
Justan Hard			
Date			
August 26, 2015			

